

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 26. NR. 3. W. . .
T 26 NR 4 W

----- Crawford ----- COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 31 and 36 . . .

DESCRIPTION OF CORNER MONUMENT Left 1 1/4" pipe in place

WITNESSES TO CORNER

7" W. Oak - N83W - 30 1/2 links

7" W. Oak - S15W 1 36 links

* 9" W. Oak - N58E - 37 1/2 links

* G.F.DeLaMater NBT

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was previously established by Marcus Schaaf,
Reg. Land Surveyor, during a survey in 1948. Corner was restored
from stumps of the government BTs, and Concurred in by DeLaMater,
whose witnesses are in evidence.

Corner was witnessed for the record October 6, 1958.

SURVEYORS SEAL

SIGNED *Kenneth J. Oetting* DATE 10/7/58
REGISTERED LAND SURVEYOR