

SURVEY &
REMONUMENTATION

APR 07 1998

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in SECTION

Crawford
(County)

Located In:

Corner Code #

1. Public Land Survey

✓ T 27NR 1W

I-13

T 28N R 1W

I-1

T R

T R

2. Property Controlling
In Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. _____, Recorded Plat

LIBER

3

5. Private Claims

PAGE 302

I, Marvin E. Myers, in a field survey on May 27, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. 1839

James H. Mullet D.S.

Mon: Post

Wit: 12" Pine N26°E 47 lks

12" Pine N1W 27 lks

GLO - 1858 W. Warner, D.S.

Mon - Post

Wit: 9" Spruce Pine S21°W 6 lks.

6" Spruce Pine S70 °E 41 lks.

Carlos LaGarica, Ausable State Forest

Mon: Intersected 18 lks North of corner

Sunk a monument

Wit: NBT 14" Spruce Pine S50°E 28 lks

NBT 14" Spruce Pine N47°E 36 lks

Pit North 1.00 chains

Took new witnesses for the County

9" J. Pine N09°E 0.75 lks

12" J. Pine N55½°E 2.56 lks

July 3, 1953 Dept. of Conservation

Mon - Set 1" Pipe by double proportion meas

Wit: 10" J. Pine N12°W 68 lks.

12" J. Pine S38°E 114 lks

L. 417, P. 606 F. King, P.S. Aug 13, 1996

Mon - Found 1¼" Pipe

Wit: 15" J. Pine S30°E 75.50

10" J. Pine S20°W 102.48

27" Oak N50°W 87.00

12" Oak N10°W 56.80

1933 F. N. Smith for G.F. Delamater

Mon - unknown

Wit: 10" S. Pine S53½°E 184 feet

Oct 6, 1989 Don Marlatt, P.S.

Mon - Found 2" Pipe in concrete

Wit: 16" J. Pine S55°W 74.1

18" J. Pine S25°E 75.61

11" Oak N15°W 56.87

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1½" Pipe in 12"x12"x6" concrete monument 0.8 deep in Road 14± South of the centerline of East Townline Road and 6± West of the centerline of Thundermug Road to the South. Found 30d nail in the West face 11" B. Oak N10°W 56.66; found King nail and tag in blaze of 32" B. Oak N44°W 87.05; found King nail and tag in SE face 10" J. Pine S26°W 102.64; found 30d nail SW face 16" J. Pine S21°W 75.67.

Replace 1½" Pipe in exact location with a Standard Crawford County Monument.

Accepted this position as the best available evidence of the position of the Original Government Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon - Standard Crawford County Monument.

Wit: Found 30d nail in West side 11" Black Oak N10°W 56.66

Found King Nail and tag in Blaze 32" Black Oak N44°W 87.05

Found King nail and tag in SE side 10" J. Pine S26°W 102.64

Found 30d nail in Southwest side 16" J. Pine S21°W 75.67

Signed by

Marvin E. Myers

Date

Dec 15, 1997

Surveyor's Michigan License No. 31600

STATE OF MICHIGAN
CRAWFORD COUNTY
RECORDED

19 DEC 97 2:36 P.M.

SANDRA MOORE
REGISTER OF DEEDS

Register of Deeds Stamp & File
Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

CRAWFORD COUNTY

PEER GROUP APPROVAL

DATE June 9, 1997

Marvin E. Myers M.R.P.

Marvin E. Myers, P.S.
County Surveyor

