

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Crawford
(County)

Located In:

Corner Code #

1. Public Land Survey

T 28N R 1W

M-5

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, Marvin E. Myers, in a field survey on OCT 18, 19 93,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

GLO - May 1839 Hodgeson & Sibley

Mon. - Post

WIT: 10" Pine S23°W 45 lks.

8" Pine N41°W 45 lks.

Consumer Power Co. Oct. 1967

Mon. - Fd. Clay Tile Mon. with Iron Pin

Nail & Blaze 6" J.Pine SE 6.91'

Nail & Blaze 4" J.Pine NE 12.92'

Nail & Blaze 6" J.Pine SW 16.33'

Nail & Blaze 6" J.Pine NW 16.36'

DNR - P.S. 10068 1979

Mon. - Fd. Clay Tile

DNR Mon.

WIT: 4" J.Pine S58°W 16.41'

4" J.Pine N68°W 16.46'

NW Cor. Sec. 18, T28N, R1E

South 81.00'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found DNR Std. pipe with aluminum cap verified location by measurement to accessories and corners of records and is
accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon. - Left in place Std. DNR Mon.

WIT: 6" Red (Norway) Pine N47°W 45.73'

4" Red (Norway) Pine N12°W 42.05'

4" Red (Norway) Pine N06°E 59.46'

10" Red (Norway) Pine N32°E 54.73'

Fd. 6" J.Pine N68°W 16.46' (lying flat)

Fd. 6" J.Pine SW 16.33' (lying flat)

STATE OF MICHIGAN

COUNTY OF CRAWFORD

FILED FOR RECORD

6th DAY OF Dec, 1993

3:20 am/pm, IN LIBER 34c

PAGE 108

Elizabeth H. Williams

Register of Deeds

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

Signed by Marvin E. MyersDate Dec 4, 1993

Surveyor's Michigan License No. 31600

DATE NOV 29, 1993

PEER GROUP APPROVAL

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

2847