

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 28 NR. 1 E.
T. 28 NR. 1 W.

Crawford - Oscoda COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 19, 20, 25

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap

WITNESSES TO CORNER

8" J. Pine - N 35 E - 2 Links

8" J. Pine - S 43 E - 97 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was established by Forestry Division survey crew, while making
a partial resurvey of this area. Corner was placed 120 Links South of Corner
common to Sections 19, 24, 25, as per Gov't. Field Notes.

Corner was placed and witnessed July 3, 1953.

SURVEYORS SEAL

SIGNED James C. DeLoater DATE 2/9/54
REGISTERED LAND SURVEYOR