MAR 2 7 1996

CRAWFORD COUNTY REMONUMENTATION

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		1	STATE OF HICHIGAN
Crawford Located (County)	d in: Corner Code #		CRAWFORD COUNTY RECORDED
1. Public Land Survey	T_28N R_3W		8 JAN 96 12:27 P.M.
2. Property Controlling S	TR		SANDRA MOORE REGISTER OF BEEDS
in Section S 3. Miscellaneous S Property in Sec. S	T R LIB	ER 3	PAGE 233
1 roporty in 300.	·	Register	of Deeds Stamp & File Numbe
4. Lot No, Recorded Plat		A B C	D E F G H I J K L
· · · · · · · · · · · · · · · · · · ·		2 6	- 5 4 3 2 1
I, <u>Wayne E. Boss</u> , in a field survey on <u>November 1</u> , 19 <u>95</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:		ove were in strong of the Law and for 6 10 10 10 10 10 10 10 10 10 10 10 10 10	-8 - 910111. -171615141. -20 - 21222324
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.		10 30	-2928272625
		11 12 -31 13	32 - 33 - 34 - 35 - 3(
A. Description of original monument an C-1 T28N-R3W	nd accessories and/or subsequent restoration:	13	
G.L.O. James H. Mullett, 1839 Ran town line between T28N-R3W and T29N-R3W setting common corners. Set post cor. Section 31 & 32 (5 & 6) 1. Beech 12" N63*W 13 2. Beech 12" N50*E 20	cor. No record of G.A.S. notes. Dean C. Delamater rewit. cor. in 1951 as stated in his land corner record. 3. 14" Red Pine N17°W 82 links (54.12')	Kenneth J. Ostling left in mon. in his DNR survey St T29N-R3W survey in 1974 Parker used cor. in 1980. 3. 17" N. Pine N19°W54.7 4. 5" N. Pine N13°E 88.21 5. 6" Maple N37°W 43.88'	ection 31, Norm 0'.
B. Description of corner evidence foun	nd and/or method applied in restoring or reesta	blishing corner:	
C-1 Fd. DNR P.A.S. mon. set by	G.A.S. and used in subsequent surveys. Can't		
6. Fd nail in 8" Poplar N50°E 9.30' 7. Fd tag in 7" high Poplar stump S55°W 5.77'		PEER GRO	D COUNTY UP APPROVAL
		mison	E. Myen
·		Count	E. Myers, P.S. Sy Surveyor
C. Description of monument for corner C-1 Fd DNR P.A.S. mon. left in	and accessories established to perpetuate loc	ating the position of the co	orner: 1444444444444444444444444444444444444
 Fd tag in 16" R. Pine N1 Fd nail in 8" Poplar N50 Fd tag in 7" high Poplar Fd spk in 6" Birch 33.80 	and accessories established to perpetuate local place. 17°W 54.56' (Also recorded as N19°W 54.70' & in the second state of the position of th	54.12') \$\frac{\partial}{\partial}\parti	WAYNE E. DOSS PROFESSIONAL GENVEYOR ON INC.
And is accepted as a careful	and faithful reestablishment of the position of	the original corner.	PROFESSIONAL CE SURVEYOR INC. 20703
Wh/	2 Sam.	/	21/35
Signed by Wayne E. Boss PS Surveyor's Michigan License No.	20703	Date	
. //			_