

**SURVEY &
REMONUMENTATION**

MAR 08 1994

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
COUNTY OF CHARLEVOIX
RECEIVED FOR RECORD

1993 DEC 10 PM 4: 28

Charlene M. Roser
REGISTER OF DEEDS

For corners in

<u>Charlevoix</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>32N</u> R <u>4W</u>	<u>D-1</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous	S _____ T _____ R _____	_____
Property in Sec.	S _____ T _____ R _____	_____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Wayne E. Boss, in a field survey on September 27, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. John Mullett
May 1840. Set 1/4 Sec. Post.
1. Hemlock 16. N.27°W.27.
2. Hemlock 12. N.82°E.10.

E.A. Robinson found 1/4
Sec. Post. Original G.L.O.
witnesses still existing
& verified.

Marcus Schaaf set pipe for
1/4 cor. (Carl Roser determined
Schaaf cor. to be erroneous
and 48.5' south of actual cor.)

December 20, 1985
Carl Roser, PS, set DNR Mon.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Fd. DNR Mon. set by Carl Roser, PS. Roser's Corner recital as recorded in Liber 2, Page 199, reads as follows:
D-1 - Restored 1/4 Cor. Mid-way & on line between Sec. Corners to E & W. Fd. Schaaf 2' pipe (set pipe down flush w/ground), N26°15'E, 57.1'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-1 Found DNR Mon. & Cedar Post per Liber 2, Page 199, Charlevoix County Records, Charlevoix County, Michigan, and is accepted as a careful and faithful reestablishment of the position of the original corner.

7" Maple	N28°W	7.1'	Fd. Blaze & Tag
9" Maple	S72°E	13.6'	Fd. Blaze & Tag
4" Maple	S28°E	23.6'	Fd. Blaze & Tag
4" Ironwood	S08°W	13.0'	Fd. Blaze & Tag
E-W Trail	North	113'±	

Signed by Wayne E. Boss Date December 9, 1993
Surveyor's Michigan License No. 20703