

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 32 N. R. 5 W.	A-8; A-9; G-12
2. PROPERTY CONTROLLING IN SECTION	19, T. 32 N. R. 5 W.	10
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S. R. E. W.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on August 25, 1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~As described on original monument and accessories established by separate certificate~~

C. (continued)

10
Drove 1"x18" pipe
5" Cedar N74°E 77.7
7" Cedar S66°E 78.1
7" Cedar S64°W 57.9
8" Tamarack N57°W 63.4
Set Cedar post w/loc. tag
Due E 33'

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- A-8 Fd. 3/8" sq. spike; replaced it with 3/4" sq/ x 12" boat spike; corner falls in center of N-S blacktop county road.
- A-9 Fd. Charlevoix co. mon. w/cap broken; added 3/4"x12" bolt w/nut in pipe; corner is in center of N-S blacktop county road; random line to east is south 5.1'.
- G-12 Restored 1/4 corner on line between fd. section corners to N & S and at prorated distance to Robinson survey on W line of Sec. 34, for road, dated June 1906, FB #C-300; corner falls 4 ft. W of center of N-S gravel road & is 16'± S of irregular B-W fence on trees (wooded) to East.
- 10 Established corner per standard B.L.M. instruction; corner falls in center of N-S b'top
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: county rd.

A-8	A-9	G-12
Fd. 3/8" B.spike & replaced w/3/4" x 12" boat spike	Set 3/4"x12" bolt & nut over county monument	Drove 1 1/4"x22" iron rod
10" Tamarack N48°E 80.0	12" Tamarack N47°E 113.3	P.Pole S78°W 32.45
8" Tamarack N74°E 57.5	10" Cedar S61°E 84.3	3" Ironwood N35°W 68.0
18" W. Pine S70°W 102.9	9" Cedar S68°W 63.0	6" Maple N83°E 61.6
6" Cedar N75°W 52.5	7" Cedar N63°W 72.0	Set cedar post w/loc. tag
Set cedar post w/loc. tag	Set cedar post w/loc. tag	Due W 33.0
Due E 33	Due E 33	

SIGNED BY Carl F. Roser 4-26-76 DATE

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

BOYNE VALLEY TOWNSHIP
CHARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 26, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET