## SURVEY & REMONUMENTATION

STATE OF MICHIGAN COUNTY OF CHARLEVOIX RECEIVED FOR DECORD

OCT 1 8 1996

96 OCT 14 AM 10: 29

COMMISSION
MANUACCININIAN

LAND CORNER RECORDATION CERTIFICATE

For corners in COMMIS	SION Filing Requirer	ment of Act 74, Mich. P.A. 197	O Charles M. Casher	
Charlevoix (County)	Located In: Corne	r Code#	REGISTER OF DEEDS	
1. Public Land Survey	T32N R <u>6W</u> 1	MC A5/A6 MC M5/M6		
Property Controlling     in Section     Miscellaneous     Property in Sec.	S TR	ther#1	Register of Deeds Stamp & File Numbe	
4. Lot No, Record	ed Plat		A B C D E E C II T T T	
J. Frivate Cialitis			2 6 5 4 3 2 1 1 1 2 2 1 1 1 1 2 2 1 1 1 1 1 1 1	
conformance with regulations and ru United States Department of the Int that the corner points mentioned in	in a field survey on Sept. 20, P.A. of 1970, the corner points menticules therefore as required in the current erior, Bureau of Land Management or blines 3, 4 and 5 above were in conform Decree of a Court of Law; establisw:	oned in lines 1 and 2 above were in manual of survey instructions of the sty a decree of a Court of Law and /or nance with the rules of the Michigan hed, re-established, monumented,	3 4 7 8 9 10 11 1: 5 6 8 17 16 15 14 13 7 7	
NOTE: Not more than 2 comes on this certificate.	s, all in the same town and range, m	1	9	
A. Description of original monu	ment and accessories and/or subs	sequent restoration:	3	
MEANDER CORNER CO	OMMON TO SEC. 18 T32N-R5	W and SEC 13 T32N-R6W		
12" Cedar on North side lake by John Hodson, D.S. 5-27-1839  E.A. Robinson shows corner No witnesses  P.S.		Nov 1958 by Mary C. Feindt P.S. #3920	10-31-1990 George J. Avendt Jr P.S.#16034 Found 3/4" Pipe & raised with T-iron N45°E 27.93' House Foundation	
		Shows corner- No witness	S18°W 24.02' 5" White Birch N14°W 15.65' 5" Cedar	
B. Description of corner evider	ce found and/or method applied in	n restoring or reestablishing corner:		
Found George J. Avendt T	-iron & cap #16034			
GLO to A-5 = 656.7'  Recorded = 700.18  Meas = 700.18'		Characia Co. Surveyor  Arvinove D  Signatura May C. Feendt  Date: 10-10-96		

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Found 3/4" pipe under T-iron. Replaced with Charlevoix County monument.

SW cor House #00110 foundation N50°E 27.91' (Rec as 27.93')

22431

Found house witness and 5" Cedar witness. 5" Birch is gone.

4" Cedar N10°W 15.65' found nail & cap #16034 in NE side (Rec as 15.65')

6" Willow S65°E 7.41' to center

1" Spruce South 10.75' to center

Burveyor's Wiichigan License No.

Bigned by

Edge of water at Deer lake South 40 feet

And is accepted as a careful and faithful reestablishment of the position of the original corner.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14,1975
REVISED JAN., 1983
REVISED OCT., 1995

LIBER 003 FAGE 51