

FEB 22 2001

**SECTION**

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

CHANDLER TOWNSHIP

**CHARLEVOIX**  
(County)

Located in:

Corner Code #

**1. Public Land Survey**

T 33N R 4W

A-4

T R

T R

T R

T R

T R

T R

T R

**2. Property Controlling  
in Section**

S

T R

S

T R

**3. Miscellaneous**

S

T R

**Property in Sec.**

S

T R

**4. Lot No. , Recorded Plat**

**5. Private Claims**

I, **JAMES E. EVANS**, in a field survey APRIL 5, 2000 do hereby state that requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**A. Description of original monument and accessories and/or subsequent restoration:**

**A-4 QUARTER CORNER COMMON TO SECTION 7 T33N -R4W AND SECTION 12 T33N-R5W**

GLO: SET QUARTER SECTION POST

Beech 12" N43E 36 lks (12.75')

Hemlock 24" S21°W 14 lks (9.24')

May 23, 1840

By: John Mullett D. S.

Michigan Conservation Dept.

10-17-1961 by Kenneth Ostling

Found old squared stake as identified

By Marcus Schaaf RLS in 1930's. Schaaf

Had found one Government BT and

One line tree.

5" Maple S17°W 18.5' (1)

8" Basswood N87° E 10.5' (2)

Carl F. Roser PS #12028 LCRC 1-12-1982

Found DNR monument added cedar post

10" Basswood (cluster) N85°E 10.3' (2)

6" Twin Maple S20°E 18.3 (1)

3" Maple N35°W 14.7

5" Maple N30°E 20.2' (3)

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner**

**A-4 QUARTER CORNER COMMON TO SECTION 7 T33N -R4W AND SECTION 12 T33N-R5W**

Found DNR monument and cedar post

Distance to A-3 2747.25' (GLO =2640.0')

Distance to A-5 2668.51' (GLO= 2640.0 DNR =2668.58')

**C. Description of monument for corner and accessories established to perpetuate location the position of the corner:**

**A-4 QUARTER CORNER COMMON TO SECTION 7 T33N -R4W AND SECTION 12 T33N-R5W**

**FOUND DNR MONUMENT AND CEDAR POST**

8" Maple S 15° W 18.38' Set nail & cap #22431 in blaze mark. (1)

12" Basswood N 86° E 10.13' Set nail & cap #22431 in blaze mark (2)

8" Maple N 35° E 20.14' Set nail & cap #22431 in SW side (3)

12" Maple N 7° W 24.68' Set nail & cap #22431 in blaze mark

And is accepted as the best available evidence of the position of the original corner.

Signed by

Surveyor's Michigan License No

22431

Date

12-07-00

Charlevoix Co. Surveyor  
**APPROVED**  
Signature *Mary C. Ferrell*  
Date: *Dec 7, 2000*

