

For corners in

Corner Code #

- | | | | | | |
|---------------------------------------|---|-----|---|----------|-----|
| 1. Public Land Survey | T | 33N | R | 5W | J-7 |
| | T | | R | | |
| 2. Property Controlling
in Section | S | 22 | T | 33N R 5W | 6 |
| | S | | T | R | |
| 3. Miscellaneous
Property in Sec. | S | | T | R | |
| | S | | T | R | |

4. Lot No. _____, Recorded Plat _____

5. Private Claims

[illegible]

A. Description of original monument and accessories and/or subsequent restoration:

6 - This corner position was not established during the original government survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

6 - Established the Northwest corner of the Southeast quarter of the Northeast quarter of Section 22 per standard B.L.M. instructions for subdivision of a section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

6 - Set 5/8" x 32" rod with PS cap and carsonite marker post.

Wit:	Set nail in 3" Beech	S 8° E	29.36'
	Set nail in 4"-8" Beech clump	N 61° E	13.28'
	Set nail in 18" triple Maple	S 76° W	47.76'
	Set nail in 9" Cherry	N 25° W	10.45'
	1-3/4" x 48" iron pipe	South	1'
	Carsonite post	North	1'

A circular professional seal for a surveyor in the State of Michigan. The outer ring contains the text "STATE OF MICHIGAN" at the top and "LICENSED LAND SURVEYOR" at the bottom, separated by two five-pointed stars. The inner circle contains the name "CARL KIIISKILA" in a bold, sans-serif font, followed by "LAND SURVEYOR" in a similar font. Below this, the text "No. 33981" is printed. The seal is surrounded by a decorative border of small dots.

Date 7-26-99