Cons. 4047 Rev. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 33 N.R. 8 W

	_	Charlevo	oix county
DESCRIPTION OF CORNER	1/4 corner common to Sections	23 and 24	
CORNER HOMMENT	ENT Set 1" x 36" pipe with brass cap 6" in road.		
DATE HORMMENT PLACED AND	WITHESSED 12/1/67		····
WITHESSES TO CORNER			
N	8 * Hemlock	N 14º 30 ' W	96.40
24	4" W. Pine	s 43° 30' B	94.601
+	8 * Klm	s 12°00' W	77.801
	AND		

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found 3" square post and rocks. Set cedar post with square top 5.00' North.

Wi corner identified by E.K.Robinson on Dec.14,1911 from U.S. Elm, 10 ,S.55 E.,19.8 ft.

Found Robinson's 3 in. square by 5 ft,long stake with stones around the stake for corner and also found his bearing trees. See County Records

Restored E&W 1 Line as established by Charlevoix County Surveyor, William Miller, on June 11th.A.D.1869 in the survey for a road, as recorded on page 31 of Marion Township Clerk's Record dated June 16,1869.

Restoration accomplished by running a straight line from \mathbb{W}_4^1 corner easgerly to a point at the intersection of old line fence with the west shore line of Nowland Lake. This line generally follows the center line of old grade.

SURVEYOR'S SEAL

SIGNED GREGORY A. SHADKO DATE 12/12/67

1934