

FEB 22 2001

STATE OF MICHIGAN  
COUNTY OF CHARLEVOIX  
RECEIVED FOR RECORD

**SECTION**

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

00 DEC 21 AM 9:09

For corners in

Charlevoix  
(County)

Located In:

Corner Code #

1. Public Land Survey

T 33N R 8W

C-9

2. Property Controlling  
in Section

S

T

R

3. Miscellaneous  
Property in Sec.

S

T

R

4. Lot No. , Recorded Plat

5. Private Claims

*Charles M. Feindt*

REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Wayne E. Boss, in a field survey on October 20, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

**A. Description of original monument and accessories and/or subsequent restoration:**

C-9 October 1841 Charles W. Cathcart D.S.  
Noted Birch 8" at corner  
No witnesses stated

Prior to 1973  
MC Feindt, P.S. found pipe probably placed by D.C. Nettleton  
No witnesses

July 1976, 1977 L.R. Feindt  
Raised to surface with T-iron  
1) Triple W Ash S22° W51.3'  
2) 20" & 14" Twin Maple S38° W82.7'  
3) Utility pole S10° E188.5'

May 23, 1980 N.B. Deyoung  
Found T-iron  
3) Power pole S07° S07° E188.5'  
1) 6" Ash S10° W52.6  
4) 11" Poplar N20° E46.2'  
5) T-iron East 33'

September 1980 NBD  
Found T-iron in center of N-S road and above witness

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

C-9 November 3, 2000  
Found bent T-iron in road  
3) Power pole S10° E 188.5' with nail and tag  
1) 6" Ash S10° W 52.60' found nail  
4) 8" Poplar N20° E 46.20' found nail  
5) T-iron East 33.0' found nail  
6) 8" Poplar N15° E 52.70' found nail and tag  
Fence to West about 115' ± South of existing corner

C-10 to C-9 GLO 40 chains (2640) measures 2648.12'  
C-9 to C-8 GLO 40 chains (2640) measures 2641.09' MLF measured 2641.68'

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**  
C-9 Placed Charlevoix County steel marker

3) Power pole S10° E 188.5' with nail and tag  
1) 6" Ash S10° W 52.60' found nail  
4) 8" Poplar N20° E 46.20' found nail  
5) T-iron East 33.0' found nail  
6) 8" Poplar N15° E 52.70' found nail and tag  
Fence to West about 115' ± South of existing corner

And is accepted as a careful and faithful reestablishment of the position of the original corner.

Signed by

Date

Surveyor's Michigan License No.

20703

Charlevoix Co. Surveyor  
APPROVED  
Signature *Mary C. Feindt*  
Date: 12-27-00

