

FEB 22 2001

SECTION

STATE OF MICHIGAN
COUNTY OF CHARLEVOIX
RECEIVED FOR RECORD

00 DEC 21 AM 9:10

Carlene B. Justice

REGISTER OF DEEDS

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Charlevoix (County)	Located In:	Corner Code #
1. Public Land Survey	T 33N R 8W	C-10
	T R	
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	19		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Wayne E. Boss, in a field survey on October 20, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-10 October 1841 Charles W. Cathcart D.S.
Section 1/4 post
1) Cedar 8" N77° W 10 links
2) Black Ash 6" N80°E 12 links

1998 Arthur Ranger, P.S.
Found nail in center line of road
3) 1/2" iron West 33.0'
4) 10" Tamerack N28°W 62.08'
5) Power pole S72°W 19.53'
6) 7" Tamerack E 55.95'
7) 12" Tamerack S40°W 59.21'

November 1999
Wayne E. Boss P.S.
Used nail as found

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-10 October 2000
Found nail at surface in C.L. N-S road
Old fence to East up the hill
3) 1/2" iron West 33.0'
4) 10" Tamerack N28° W 62.08'
5) Power pole S72°W 19.53'
6) 7" Tamerack E 55.95'
7) 12" Tamerack S40° W 59.21'

Charlevoix Co. Surveyor
APPROVED
Mary C. Ferritt
Date: 12-7-00

C-11 to C-10 GLO 40 chains, measures 2638.51',
C-10-C-9 GLO 40 chains (2640') Measures 2648.12'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
C-10 Placed Charlevoix County steel marker and monument box

3) 1/2" iron West 33.0'
4) 10" Tamerack N28° W 62.08'
5) Power pole S72°W 19.53'
6) 7" Tamerack East 55.95'
7) 12" Tamerack S40° W 59.21'

And is accepted as a careful and faithful reestablishment of the position of the original corner.

Signed by _____
Surveyor's Michigan License No. _____

Date 12/15/2000

