REMONUMENTATION

FEB 2 2 2001

STATE OF MICHIGAN COUNTY OF CHARLEYOIX RECEIVED FOR FIGORD

| | | R RECORDATION CER ement of Act 74, Mich. | TIFICATE P.A. 1970 | 00 DEC 21 AI | 4 9: 00 |
|--|--|--|--|---|--|
| For corners in SECTION | i mig itoqui. | | | Howare Po. | herton |
| Charlevoix Locate (County) | d In: | Corner Code # | | REGISTER OF C | DEEDS |
| 1. Public Land Survey T_S T_ T_ | 33N R 8W <u>E</u> R | -2 | | | |
| 2. Property Controlling S T In Section S In Section S In Section S In Section S In Sec | R R R | | Reg | ister of Deeds Sta | .mp & File Number |
| 4. Lot No, Recorded Plat | | | АВ | CDEFG | нілкь |
| 5. Private Claims | | | 2 - 6 | 5-4-4- | -3-2-1- |
| **** | | | 3 | B 9 9 | _101112 |
| I, Wayne E. Boss , in a field survey requirements of P.A. 74, Michigan P.A. of 197 were in conformance with regulations and rules instructions of the United States Department of to a Court of Law and /or that the corner conformance with the rules of the Michigan Bos established, re-established, monumented, recover | O, the comer points therefore as required the interior, Bureau of points mentioned in the difference of Land Surveyo | mentioned in lines 1 and 2 red in the current manual of 5 Land Management or by a 1 lines 3, 4 and 5 above we are or by a 2 Decree of a Court of the | under 5 ——18 survey 7 ——19 decree vere in 8 ——19 | 20 21 | -15 - 1413 |
| NOTE: Not more than 2 corners, all in the on this certificate. | same town and r | ange, may be recorded | 11 12 13 | 32-33- | _343536_ |
| A. Description of original monument a restoration: E-2 October 22, 1841 Charles W. Calhcart, D.S. Set 1/4 post 1)Lynn 14" East 4 links (2.64") 2)Lynn 10" S80"W 12 links (7.92') | . June 1 | and/or subsequent 978 L.R. Feindt, P.S. 1 1/2" pipe | | | |
| August 12, 1985 N.B. Deyoung, P.S. Found 1 1/2" pipe 3) 18" Maple North 71.10" 4)14" Maple S 55" E54.65" 5)16" Maple S 40" E 44.55" 6)6" Poplar S 20"W 27.45" | | | Charle A I Signature Dat | voir On, Cutyl 10/10/1150 10:12-17-00 | Earnolt |
| B. Description of corner evidence found E-2 November 7, 2000 Found 1 1/2" pipe 8' South of center line of East-3) 30" Maple N71.10' found nail 4) 20" Maple S55" E 54.65 found nail 5) 23" Maple S40" E 44.55 found nail 6) 12" Poplar S20" W 27.45' found nail | | pplied in restoring or rees | tablishing corne | r. | |
| E-3 to E-2 GLO 40 chains (2640') measures 264 E-2 to E-1 GLO 39 chains (2574') measures 258 | 6.30 | | | | |
| C. Description of monument for corner at E-2 Placed Charlevoix County steel marker 3) 30" Maple N71.10" found nail 4) 20" Maple S55" E 54.65 found nail 5) 23" Maple S40" E 44.55 found nail 6) 12" Poplar S20" W 27.45" found nail | nd accessories es | stablished to perpetuate lo | cating the positi | on of the corner: | |
| And is accepted as a careful and faithful reestable Signed by Surveyor's Michigan License Mo. | ishment of the position | on of the original corner. Date | 12/15/2 | .000 | |
| TO PROPER | The second secon | FORM APPRO | /ED BY MICHIGAN STATI | E BOARD OF PROFESSIONA | U. SURVEYORS, JAN. 28, 197 WEDVERD, MAY 14, 137 |
| The state of the s | LIBE | R 004 FAUE 01 | | | REVISED MAY 14,137 REVISED JAN., 1 REVISED OCT., 1 |