1 FEB 0 4 1999

SECTION

Signed by

Surveyor's Michigan License No.

STATE OF MICHIGAN COULTY PLEVOIX REPLANTED AND CORD

98 DEC 28 PH 12: 24

LAND CORNER RECORDATION CERTIFICATE Charles M. Baker Filing Requirement of Act 74, Mich. P.A. 1970 REGISTER OF DEEDS For corners in Charlevoix Located In: Corner Code # 1. Public Land Survey 2. Property Controlling in Section 3. Miscellaneous Register of Deeds Stamp & File Number Property in Sec. , Recorded Plat 4. Lot No. 5. Private Claims NOV 98 Wayne E. Boss 19 do hereby state that under in a field survey on requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in 5 conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, ค recovered, found as expressed below: 9 NOTE: Not more than 2 comers, all in the same town and range, may be recorded 10 on this certificate. 1 1. A. Description of original monument and accessories and/or subsequent restoration: 7)11"MAPLE \$45*W 40.40' JULY 1949, MARY C. FEINDT L-7 OCTOBER 21, 1841 8) STOP SIGN S45*E 37.50' Ch.W.CATHCART, DEPUTY SURVEYOR FD. IRON NO WITNESSES MAY 11, 1989, G.J.AVENDT JULY 1959, MARY C. FEINDT PLACED POST FOUND IRON NO WITNESSES FOUND T-IRON 1) CEDAR 8 INCH NORTH 6 LINKS 6)16"MAPLE N60*W 43.55' 2) HEMLOCK 10 INCH S4*E 15 LINKS MAY 5, 1981, A. A. RANGER 7)20" MAPLE S65*W 39.85' FOUND IRON NO WITNESSES SEP. 16, 1879 D.C.NETTLETON 5)30" MAPLE N45*E 27.14' OCT. 10, 1988, J.E.FERGUSON PLACED POST AT 40.66 CHAINS FD.T-IRON 5)16"MAPLE N30E27.85 HEMLOCK 22" N21*W 22.5 LINKS. 6)10"MAPLE N60W 43.95' BEECH 20" \$45*30'E 34 LINKS Description of corner evidence found and/or method applied in restoring or reestablishing corner: **NOVEMBER 13, 1998** L-7 FOUND T-IRON IN CENTER LINE OF EAST WEST ROAD AND CENTER LINE OF ROAD TO SOUTH FOUND 5/8" ROD 8" UNDER SURFACE 5) 30" MAPLE N45*E 26.97' PK NAIL WITH ART RANGER TAG, ALSO 28.86' L.R.FEINDT NAIL & CAP 6) 16" MAPLE N60*W 43.55' NAIL OVER GROWN 8) STOP SIGN S45*E 37.50" M-7 TO L-7 G.L.O. 40 CHAINS (2640'), D.C.NETTLETON 2683.56 MEASURES 2682.04' L-7 TO K-7 G.L.O. 40 CHAINS (2640') D.C.NETTLETON 2683.56' MEASURES 2683.06' C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Charlevoix Co. Surveyor PLACED HARRISON MONUMENT AND CAST IRON MONUMENT BOX L-7 APPROVED 5) 30" MAPLE N42*E 26.97' PK NAIL, ALSO 28.86' NAIL & CAP L.R.FEINDT Signaturo Mary C. Fainds 6) 18" MAPLE N54*W 43.89' SET NAIL & TAG Date: Val 2719.25 8) STOP SIGN \$25*E 38.30* 9) ELECTRIC POLE S60*W 57.45' SET NAIL & TAG AND IS ACCEPTED AS A CAREFUL & FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER E OF Minn

LIBER 003 PALE 226

FORM APPROVED BY MICHIGAN STATE PORTED OF PROFESSIONAL SURVEYORS, JAN. 28

REVISED MAY 1

REVISED JAN

REVISED JAN

REVISED JAN

REVISED OCT

20703

Date