

DEC 18 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED
OCT NOV 22 PM 2:31

For corners in

Dickinson (County)	Located In:	Corner Code ##
1. Public Land Survey	T 39N R 29W	J-3
J-3 2 33 34	T 39N R 29W	G-1
11 G-1 4 3	T R	
	T R	
2. Property Controlling	S T R	
in Section	S T R	
3. Miscellaneous	S T R	
Property in Sec.	S T R	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, James H. Moore, in a field survey on September 6, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

J-3 Original Corner - Post Set by J. H. Mullet 1849	G-1 Original Corner - Post Set by H. Brevoort 1848
Original Bearing Trees	Original Bearing Trees
16" W. Pine N01°E 52 Links	10" Birch N66°E 22 Links
18" W. Pine S01°E 31 Links	8" Birch N20°W 24 Links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J-3 Found 2" Iron Pipe With 3 Bearing Trees as Per Sundberg, Carlson's Notes	G-1 Found 1-3/4" O.D. Iron Pipe Located at Fence Corner With One BT as Per Sundberg, Carlson's Notes
Located on North-South Fence Line, 144' North of North Edge of Pine Creek	Fences Run East, West and South
Record Research On File With Register of Deeds	Record Research On File With Register of Deeds

ACCEPTED BY THE DICKINSON COUNTY
SURVEY PEER GROUP AS THE OFFICIAL
CORNER UNDER MICHIGAN PUBLIC ACT
345 OF 1990 AT A MEETING HELD ON

11-20-95

R.E.P.

COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-3 Set New Dickinson County Capped Aluminum Monument. Monument Stamped to Identify Corner. Referenced as Follows:	G-1 Set New Dickinson County Capped Aluminum Monument on North Side of Existing 1 1/2" Pipe. Monument Stamped to Identify Corner. Referenced as Follows:
6" Spruce S80°E 35.70'	Carsonite Rail North 2.0'
6" Cedar S30°W 27.32'	6" Cherry S85°E 47.84'
5" Sugar N82°W 20.85'	8" Cherry S06°W 22.06'
6" Spruce N55°W 34.04'	10" W. Birch N80°W 109.95'
Carsonite Rail North 0.75'	

Signed by James H. Moore
Surveyor's Michigan License No. 28423

Date 11/20/95

