

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Dickinson

(County)

Located In:

Corner Code #

1. Public Land Survey

T R
T R
T R
T R

2. Property Controlling
in Section

S 21 T 40N R 29W REF 25' S of F8
S 21 T 40N R 29W REF 80' W of F8

3. Miscellaneous
Property in Sec.

S T R
S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

Nov 01 2000

I, Paul R. Bressette, in a field survey on , 20 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:
(25' S of F8) Witness monument 25 feet south of Center Quarter corner of Section 21.
(80' W of F8) Witness corner 80 feet west of Center quarter corner of Section 21.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(25' S of F8) Center quarter corner of Section 21 falls in pond. Set witness corner 25 feet south of corner position on the north-south quarter line of Section 21.

(80' W of F8) Center quarter corner of Section 21 falls in pond. Set witness corner 80 feet west of corner position on the east-west quarter line of Section 21. Boulder witness is black granite 3 feet by 5 feet by 3.5 feet with X chiseled on highest spot.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
(25' S of F8) DNR monument (80' W of F8) DNR monument

11" Cedar S82E 79.75' (WC,BT)

X N end culvert S66E 67.1'

06" Cedar S50E 60.0' (WC,BT)

X S end culvert S49E 70.9'

X N end culvert N58W 17.35'

1" iron pipe w/ cap S45W 24.98'

X S end culvert S67W 24.05'

X in boulder N29W 26.45'

DNR monument N63W 84.27'

DNR monument S63E 84.27'

All trees are blazed, scribed and painted. Measurements are to nail in side of tree, chiseled X or punch mark, bearings are magnetic.

All objects have a chiseled X, iron pipe has plastic cap "MI DNR 37270", bearings are magnetic.



Signed by Paul R. Bressette

Date

Surveyor's Michigan License No. 37270

For the Michigan Department of Natural Resources - Forest Management Division