RECORDED

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1098 DEC 14 PH 12: 24

For comers in			
Dickinson	Located In: Corner Code #		REGISTER OF DEEDS
City of R 1. Public Lan	T40NR 31W J-13 T_R 21=13 T_R	_	SURVEY & REMONUMENTATION
2. Property C			APR 0 2 1999
3. Miscellane Property in	eous S <u>T_R</u>		Register of Deeds Stamp & File Number
4. Lot No 5. Private Cl	, Recorded Plataims		A B C D E F G H I J K L M 2 6 5 4 3 2 1
requirements of conformance wi United States D that the corner Board of Land recovered, foun	F. Perkins, in a field survey on Oct. 8, 1998 P.A. 74, Michigan P.A. of 1970, the corner points mentioned in line the regulations and rules therefore as required in the current manual department of the Interior, Bureau of Land Management or by a decrepoints mentioned in lines 3, 4 and 5 above were in conformance with Surveyors or by a Decree of a Court of Law; established, read as expressed below:	tes 1 and 2 above were if survey instructions of the of a Court of Law and the rules of the Michi established, monumen	fe in 5 19 17 16 15 14 13 19 19 19 19 19 19 19
	more than 2 corners, all in the same town and range, may be n is certificate.	ecorded :	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
J-13	on of original monument and accessories and/or subsequent South & Corner Section 35 Post by James H. Mullett, D.S. 1846 Original Bearing Trees Birch 8 N50°E 18 Lk. Maple 4 N31°W 7 Lk.	t restoration: I–13	S.E. Corner Section 34 Post by James H. Mullett, D.S. 1846 Original Bearing Trees Spruce Pine 6" N21°E 13 Lk. Spruce Pine 6" N66°W 11 Lk.
B. Descript	ion of corner evidence found and/or method applied in resto	oring or reestablishin	ng corner:
	No Evidence of Original Corner or Accessories Remains. Found Capped Iron Pipe ± 3" below Asplin Centerline Woodward Ave. as referre to in Certificate #429.	I-13	
C. Descripti	on of monument for corner and accessories established to	perpetuate locating t	the position of the corner: Accepted above Pipe as Best Remain-
Signed by _	stablean Licence No. 12027	Fag ail/Tag	ing Evidence of Corner Location. Placed 3½ " Stamped D.C. Remon. Corner inside Existing I" Iron Pipe and installed Monument Box. New Witnesses Aspen 4" N37°W(M.B.) 81.00' Nail/Tag R.Pine 14" S36°W(M.B.) 53.70' Nail/Tag Nail-Top Fence Post N42°E(M.B.) 72.3 NW Flange Nut-F.H. S40°E(M.B.) 39.80 Placed Carsonite Marker 34.60' South
ourveyors N	SURVEY PEER GROUP AS THE OFFECASE NO.	N SURVILLE	MY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1871 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1996 R. 2 Page 400

COUNTY REPRESENTATIVE