## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T 41 NR 28 W

		· ·	Dickinson	COUNTY
DESCRIPTION	OF CORNE	R 1/4 corner bet	ween Sec. 1 28-33	
DESCRIPTION	OF CORNER	MONUMENT_1"	pipe with 4" bress	cap
WITNESSES	TO CORNER	17" Red Pine	N 72° W 1/4 S NBT	135_linke
		6" Aspen	N 4° W	78 links
			"1/4 S NBT"	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-established 1/4 corner midway and oh line between two section corners.

Found no evidence of original corner.

Corner lies on west shoulder of logging road.

Corner placed and witnessed January 2, 1958.

SURVEYORS SEAL

SIGNED Silly & Suchler DATE 1/13/58 PREGISTERED LAND SURVEYOR