

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

(DICKINSON COUNTY)

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____ T. <u>41</u> N. <u>X</u> S., R. <u>28</u> W.		B-7
2. PROPERTY CONTROLLING IN SECTION <u>20</u> , T. <u>41</u> N. <u>X</u> S., R. <u>28</u> W.		#3
3. MISCELLANEOUS PROPERTY IN SECTION _____, T. _____ N. _____ S., R. _____ E. _____ W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 10, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner B7 (1/4 corner between Sections 18 & 19, T41N, R28W):

Y. Birch post (Not found. No subsequent monuments found.)
Hemlock 30 S62E 18 (Not found. No subsequent accessories found.)
Y. Birch 10 N25W 12 (Not found. No subsequent accessories found.)

Corner 3 (North 1/16 corner between Sections 19 & 20, T41N, R28W):

Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner B7: Restored proportionately on line between Sec. Cor. 40.114 ch. E and Sec. Cor. 41.257 ch. W.

Corner 3: Established on line between Sec. Cor 19.998 ch. N and 1/4 cor. 19.998 ch. S.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner B7: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
Sugar Maple 5 N30°W (mag.) 42.4 ft. "1/4S, NBT"
W. Spruce 8 S45°E (mag.) 18.2 ft. "1/4S, NBT"
Declination is 0°45' West.

Corner 3: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
Aspen 10 N42°W (mag.) 10.3 ft. "1/16S, BT"
Aspen 8 S83°E (mag.) 12.5 ft. "1/16S, BT"
Declination is 0°20' West.

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Arthur O. Enger CHIEF OF SURVEY PARTY
MICHIGAN REGISTERED LAND SURVEYOR
Arthur O. Enger
Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

