

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #
(County)		
NORWAY TOWNSHIP		
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling Section	S 16 T 41N R 29W	09
	S 16 T 41N R 29W	12
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

7/31/2013AD
Jeremy J. Pipp, in a field survey on 7/31/2013AD do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(09) Center-East One-Sixteenth corner of Section 16. Not set in original survey, no evidence of subsequent establishment.

(12) Center-South One-Sixteenth corner of Section 16. Not set in original survey, no evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(09) Corner position established mid-point and on-line between the Center One-Quarter corner and the East One-Quarter corner of Section 16.

(12) Corner position established mid-point and on-line between the Center One-Quarter corner and the South One-Quarter corner of Section 16. Monument falls in alder opening.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(09) DNR monument
2" Cherry N42E 17.89' (1/16S,BT)
3" Spruce S44E 74.55' (1/16S,BT)
3" Spruce S46E 77.38' (1/16S,BT)
5" R. Pine S64W 112.7' (1/16S,BT)

All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

(12) DNR monument
1" pipe North 6.96' (- , -)
6" Tamarack East 91.10' (1/16S,BT)
8" Tamarack S89E 77.40' (1/16S,BT)
1" Pipe South 3.14' (- , -)

All trees are blazed, scribed, painted, and tagged. Measurements are to nail in side of tree, bearings are magnetic.

Signed by _____
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, Forest Resources Division

JEREMY J. PIPP
PROFESSIONAL SURVEYOR
August 08, 2013