

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 41. NR. 29. W

Dickinson COUNTY

DESCRIPTION OF CORNER 1/4 corner for sections south side 31

DESCRIPTION OF CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap

WITNESSES TO CORNER 6" Soft Maple (1/4" NBT) N 57° E 52 Links

5" Soft Maple (1/4" NBT) N 64° W 48 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. This corner was re-established by proportionate measurement to east and
west on line between section corners.

Corner was placed and witnessed May 5, 1960.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR
Billy D. Buckler

DATE 9/13/60