

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T42, 43 NR 26 & 27 W

Marquette

Dickinson COUNTY

DESCRIPTION OF CORNER Corner common to Section 31, T43N R26W; Section 36,
T43N R27W; Section 1, T42N R27W; Section 6, T42N R26W.

DESCRIPTION OF CORNER MONUMENT 1" iron pipe with 4" brass cap.

WITNESSES TO CORNER Cedar 10" N 82 E 10 1/2 links, marked S 31 NBT

Cedar 10" S 27 E, 17 links, marked S 6 NBT

Cedar 10" S 56 W, 23 links, marked S 1 NBT

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

Replaced corner from 1 original cedar bearing tree (8" N 47 W 19 links), down,
with scribe marks plain on description face. Scar of BT face plain but no scribe
marks evident. Old 1 1/2" iron pipe in place with two old stake points. Old cruiser's
witness tree nearby and 1" pipe about 4' to south. No sign of other cedar bearing
trees. Was advised of evidence of original corner by Father Conrad Suda, Perronville,
Michigan.

Corner placed and witnessed on June 17, 1963, with William J. Mahalak.

SURVEYORS SEAL

H. S. Peterson

SIGNED H. S. Peterson
REGISTERED LAND SURVEYOR

DATE 6-17-63