

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Dickinson	Located In:	Corner Code #
(County)		
ELCH TOWNSHIP		
Public Land Survey	T 42N R 29W	F05
	T 42N R 29W	G06
	T R	
Property Controlling	S T R	
Section	S T R	
	S T R	
Miscellaneous	S T R	
Property in Sec.	S T R	

Lot No. , Recorded Plat
Private Claims

Jeremy J. Pipp, in a field survey on 6/23/2014 do hereby state

that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

3. Description of original monument and accessories and/or subsequent restoration:

F05) Quarter corner common to Sections 9 and 16. 1849: John Burt, DS. Set Cedar quarter section corner post witnessed by Cedar 14 N55E 35 links (23.10'), Cedar 12 S59W 36 links (23.76'). 1977: Michigan DNR (Arthur Enger PS#13581) Set 1" pipe with 3 3/4" Aluminum cap by proportionate method witnessed by 5" Sugar N07E 14.1', 5" Sugar S52E 3.3'.

G06) Quarter corner common to Sections 15 and 16. 1849: John Burt, DS. Set Sugar quarter section corner post witnessed by Lynn 14 N14W 60 links (39.60'), Lynn 12 S43E 31 links (20.46'). 1977: Michigan DNR (Arthur Enger PS#13581) Set 1" pipe with 3 3/4" Aluminum cap by proportionate method witnessed by 6" Sugar N80E 8.1', 8" Sugar S88W 33.8'.

4. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F05) Accepted found MDNR Monument and Two NBT Witness (both living). Position is accepted as a careful and faithful REESTABLISHMENT of the position of the original corner.

G06) Accepted found MDNR Monument and remains of Two NBT Witnesses (now stump mounds). Position is accepted as a careful and faithful REESTABLISHMENT of the position of the original corner.

5. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F05) DNR monument
EX 7" Maple N05E 14.09' (1/4S,NBT)
EX 8" Maple S39E 3.53' (1/4S,NBT)
12" Maple S09W 11.21' (1/4S,NBT)
3" Maple N51W 31.02' (1/4S,NBT)

All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Carsonite rail was set East 0.75 feet.

Signed by
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources

(G06) DNR monument
6" Elm N72E 11.45' (1/4S,NBT)
4" Maple S34E 34.32' (1/4S,NBT)
5" Ironwood S36W 23.97' (1/4S,NBT)
4" Basswood N62W 24.44' (1/4S,NBT)

All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Carsonite rail was set West 1.5 feet.

Signed by
Date July 15, 2014

JEREMY PIPP
PROFESSIONAL SURVEYOR
No. 50447

FORM 50447-ED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Revised Oct., 1995