

LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

<u>Dickinson</u>	Located In:	Corner Code #
(County)		
West Branch Township		
1. Public Land Survey	T 43N R 27W	L10
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S 25 T 43N R 27W	9
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Jeremy J. Pipp, in a field survey on 8/20/2012AD do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- (L10) Center One-Quarter Corner of Section 25. Not set in original survey.
- (09) Center-East One-Sixteenth corner of Section 25. Not set in original survey, no evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- (L10) Corner position established at the intersection of the North-South and East-West One-Quarter lines of Section 25.
- (09) Corner position established mid-point and on-line between the Center One-Quarter corner and the East One-Quarter corner of Section 25.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J06)	DNR monument	(09)	DNR monument
4" Sugar	N83E 13.92' (1/4S,BT)	8" Sugar	N80E 3.03' (1/16S,BT)
6" Sugar	S09E 6.45' (1/4S,BT)	8" Sugar	S48E 28.16' (1/16S,BT)
5" Sugar	S84W 22.11' (1/4S,BT)	6" Sugar	S47W 16.78' (1/16S,BT)
7" Sugar	N39W 16.82' (1/4S,BT)	5" Sugar	N51W 28.33' (1/16S,BT)

All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

Signed by Jeremy J. Pipp August 29, 2012
 Surveyor's Michigan License No. 50447

