

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #
(County)		
WEST BRANCH TOWNSHIP		
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling Section	S 10 T 43N R 27W	10
	S 10 T 43N R 27W	11
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

6/25/2013AD  
6/25/2013AD  
do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(10) South One-Sixteenth corner common to Sections 9 and 10. Not set in original survey, no evidence of subsequent establishment.

(11) Southwest One-Sixteenth corner of Section 10. Not set in original survey, no evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(10) Corner position established mid-point and on-line between the West One-Quarter corner and the Southwest corner of Section 10.

(11) Corner position established at the intersection of the South and West One-Sixteenth lines of Section 10.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(10) DNR monument  
6" Cherry N70E 16.67' (1/16S,BT)  
4" Balsam S78E 35.00' (1/16S,BT)  
6" Maple S04W 13.32' (1/16S,BT)  
4" Ironwood N04W 12.60' (1/16S,BT)

All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

Signed by \_\_\_\_\_  
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources

(11) DNR monument  
5" Spruce N82E 11.97' (1/16S,BT)  
14" Cedar S31E 23.91' (1/16S,BT)  
13" Cedar S81W 31.90' (1/16S,BT)  
12" Cedar N11W 14.93' (1/16S,BT)

All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

Date August 08, 2013

