

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T^{43N}₄₄ R 27W
T₄₄ NR 27W

Dickinson

COUNTY

Section corner common to sections 2 and 3 T^{43N} R27W and
sections 34 and 35 T^{44N} R27W

DESCRIPTION OF CORNER -----

DESCRIPTION OF CORNER MONUMENT 1" pipe and 4" brass cap -----

WITNESSES TO CORNER white pine 26" S 46 W 16 links -----

white pine 12" N 24 E 54 links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was replaced from original yellow pine (norway pine) bearing tree
in fair condition. " BT " notch plain. No scribe marks visible. Found two old stake
points in ground 5 links east of corner.

Corner was found while cruising timber in this area.

Corner was placed and witnessed on 18 July 1956

SURVEYORS SEAL

Henry S. Peterson

Henry S. Peterson

SIGNED -----
REGISTERED LAND SURVEYOR

7/19/56
DATE -----