

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Dickinson	Located In:	Corner Code #
(County)		
EST BRANCH TOWNSHIP		
Public Land Survey	T R	
	T R	
	T R	
Property Controlling	S 12 T 43N R 28W	12
Section	S 12 T 43N R 28W	14
	S T R	
Miscellaneous	S T R	
Property in Sec.	S T R	

Lot No. , Recorded Plat
Private Claims

6/04/2014
Jeremy J. Pipp, in a field survey on 6/04/2014 do hereby state
at under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
structions of the United States Department of the Interior, Bureau of Land Management or by a decree of
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
e rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
-established, monumented, recovered, found as expressed below:

OTE: Not more than 2 corners, all in the same town and range, may be recorded
n this certificate.

Description of original monument and accessories and/or subsequent restoration:

12) Center-South One-Sixteenth corner of Section 12. Not set in original survey, no evidence of
ubsequent establishment.

14) South One-Sixteenth corner common to Sections 12 and 7. Not set in original survey, no
vidence of subsequent establishment.

i. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

12) Corner position established mid-point and on-line between the Center One-Quarter corner and
the South One-Quarter corner of Section 12. Monument is +/-6 feet West of Centerline of N-S Road,
+/- 20 Feet North of Centerline of Roadway East, and 6 inches below road surface.

14) Corner position established mid-point and on-line between the East One-Quarter corner and the
Southeast corner of Section 12.

2. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(12) DNR monument
19" Spruce N52E 44.39' (1/16S,BT)
3x6 wood gate post S53E 54.67' (- , -)
4" Spruce S60W 31.80' (1/16S,BT)
8" Spruce N43W 44.98' (1/16S,BT)
All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Signed by
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources Forest Resource Division

(14) DNR monument
5" Ironwood N53E 26.43' (1/16S,BT)
8" Maple S64E 57.59' (1/16S,BT)
8" Ironwood S15W 8.55' (1/16S,BT)
8" Ironwood N63W 19.15' (1/16S,BT)
All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.



Date July 9, 2014