## STATE OF MICHIGAN DEPARTMENT OF **NATURAL RESOURCES**

## LAND CORNER RECORD

			Dickinson		_COUNTY
		T	43 N	R	28 W
ESCRIPTION OF CORNER	Section Corner 5, 6, 7, and 8				
ORNER MONUMENT 19	I.D. x 36" iron pipe with 4" al	umi	num cap		
NATE MONUMENT PLACED AND	WITNESSED September 15, 1969	9			
ITNESSES TO CORNER	SE corner of main part of co	one	rete block	cab:	in
N	N62 E 2,229 ch.				
	3½" iron gate pest N782°E 0	.19	3 ch.		
	·				
	AND				
	AND				
CIRCLE CORNER REGISTER	RED				

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found a 12 mx12 angle iron purporting to be the corner. Corner perpetuated as found. Angle iron set by unknown surveyor and appears to have been placed many years previously. Position checks for alinement and proportionate distances to corners 1/2 mile west and 1 mile east, but distance north to township line is 48 links longer than original record distance.

SURVEYOR'S SEAL

**DISTRIBUTION:** 

SIGNED

February 1, 1972

Arthur O. Enger

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68