

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N. R. 28W


Dickinson COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ Corner for Sections 21 and 28.

CORNER MONUMENT 1" Iron pipe with 4" Aluminum Cap and wood post.

DATE MONUMENT PLACED AND WITNESSED 2-11-63

WITNESSES TO CORNER..... 7" Cedar (N.B.T.) ($\frac{1}{4}$ S.) S. 07° E., 13 lks.



5" Balsam (N.B.T.) ($\frac{1}{4}$ S.) S. 74° W., $03\frac{1}{2}$ lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was placed on line and midway bet. Section Cors. No original evidence.

SURVEYOR'S SEAL

SIGNED Billy D. Buckles DATE 10/7/83
REGISTERED LAND SURVEYOR