

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #
(County)		
Felch Township		
1. Public Land Survey	T 43N R 29W	J05
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Jeremy J. Pipp, in a field survey on 5/28/2012AD do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(J05) Quarter corner common to Sections 11 and 14. 1848: Harvey Mellen, DS. Set Hemlock post witnessed by White Pine 20 S41E 35 links (23.10'), White Pine 18 N55W 10 links (6.60'). 1994: Michigan DNR (Stephan Szyszkoski PS#33986) Remonumented the corner at record bearing and distance from the remains of the original bearing trees, W. Pine stump bottoms of proper size S41E 35 links, and N55W 10 links. Placed a 1"I.D.x32" iron pipe capped with a 4" dia. cast aluminum MDNR tablet witnessed by 3" Spruce S43W 44.6', 6" Spruce N31W 53.5', 8" Spruce N30E 45.0', 4" Spruce S78E 45.0', Squared a 5" Aspen S26E 2.7'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(J05) Accepted found MDNR Monument and Four existing Witnesses (all living). Left MDNR monument in place and rewitnessed (added nails & signs). Accepted found MDNR Monument and Witnesses as a careful and faithful PERPETUATION of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J05) DNR monument
EX. 14" Spruce N30E 45.22' (1/4S,NBT)
EX. 7" Spruce S76E 45.20' (1/4S,NBT)
EX. 10" Spruce S47W 44.65' (1/4S,NBT)
EX. 11" Spruce N29W 53.62' (1/4S,NBT)
All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A carsonite rail was set North 1.5 feet.

Signed by

Surveyor's Michigan License No.

50447



Date

July 19, 2012

For the Michigan Department of Natural Resources, Office of Land and Facilities