

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson (County) Located In: Corner Code #
1. Public Land Survey T 43N R 29W F11
T 43N R 29W G11
2. Property Controlling Section S T R
S T R
S T R
3. Miscellaneous Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M). Contains numbers 1-36 and two dots at row 11, column 33.

2/27/2013AD
Jeremy J. Pipp, in a field survey on 2/27/2013AD do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F11) Quarter corner common to Sections 28 and 33. 1848: Harvey Mellen, DS. Set
Willow post witnessed by: Spruce 10 N27W 13 links (8.58'); Cedar 6 S25E 4 links
(2.64'); 1980: Michigan DNR (Arthur Enger PS#13581) Set 1" Pipe with 3 3/4"aluminum cap
witnessed by Cedar 12 S57E 22.3', Cedar 6 S72W 9.2' .

(G11) Section corner common to Sections 27, 28, 33, and 34. 1848: Harvey Mellen, DS.
Set Cedar post witnessed by: Sugar 12 S57E 13 links (8.58'), Sugar 10 N60W 19 links
(12.54'); 1980: Michigan DNR (Arthur Enger PS#13581) Set 1" Pipe with 3 3/4"aluminum
cap witnessed by W. Spruce 14 S42 1/2E 26.6', W. Spruce 12 N27E 51.1', W Pine 28 S30W
39.6', Cedar 8 N36W 90.1' .

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F11) Accepted found MDNR Monument and remains of two downed NBT witnesses as a careful
and faithful REESTABLISHMENT of the position of the original corner. NOTE: also found
an old signature tree N68W +/-40 feet.

(G11) Accepted found MDNR Monument and Four existing witnesses as a careful and
faithful REESTABLISHMENT of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F11) DNR monument
6" Cedar N43E 17.18' (1/4S,NBT)
4" Spruce S86W 16.30' (1/4S,NBT)
14" Cedar N71W 50.25' (1/4S,NBT)
7" Maple N21W 51.85' (1/4S,NBT)
All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic. A
Carsonite rail was set North 1.5 feet.
(G11) DNR monument
EX 17" Spruce N32E 51.24' (S27,NBT)
EX 19" Spruce S39E 27.27' (S34,NBT)
EX 33" W. Pine S35W 40.14' (S33,NBT)
EX 8" Cedar N31W 90.31' (S28,NBT)
All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic. A
Carsonite rail was set North 1.5 feet.

Signed by [Signature] Date July 30, 2013
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources

