## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

_			_		4	
E.	CO	rn	e	7	н	١.

Dickinson	_ Located In:	Corner Code #					
(County) :LCH TOWNSHIP							
Public Land Survey	TR		<u>11</u>				
	TR						
Property Controlling	T R S 19 T 43N R 29W	06					
Section	S 19 T 43N R 29W	09					
200000	S T R						
Miscellaneous	STR						
Property in Sec.	STR						
L.A.M. D.	and d Dist		Register of Deeds Stamp & File Number				
	corded Plat	<del></del>	ABCDEFGHIJKL	М			
. Private Claims	6/13/30	1.4	2 6 5 4 3 2 1 -				
	6/12/20	14	3 1 1 1 1 1 1				
Jeremy J. Pipp , ir	n a field survey on 6/11/20	do hereby state					
at under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2							
ove were in conformance with regulations and rules therefore as required in the current manual of survey 5							
structions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 18 17 16 15 14 13							
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7  e rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8 199 20 21 22 23 24							
-established manumented recovered found as expressed below:							
,,,	,		9	_			
OTE: Not more than 2 corn	ners, all in the same town and range	may be recorded	10 30 29 28 27 26 25	_			
a this cortificate							
, and act thindice.			12 31 33 34 35 36				

- . Description of original monument and accessories and/or subsequent restoration:
- 06) Northeast One-Sixteenth corner of Section 19. Not set in original survey, no evidence of ubsequent establishment.
- 09) Center-East One-Sixteenth corner of Section 19. Not set in original survey, no evidence of ubsequent establishment.
- . Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 06) Corner position established at the intersection of the North and East One-Sixteenth lines of Section 19.
- 09) Corner position established mid-point and on-line between the Center One-Quarter corner and the East One-Quarter corner of Section 19.
- .. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(06)	DNR monument	(09) DNR monument		
¦" Maple	N72E 11.56' (1/16S,BT)	11" Spruce N36E 17.48' (1/16S,BT)		
12" Maple	S22E 7.54' (1/16S,BT)	10" Spruce S75E 62.28' (1/16S,BT)		
'" Maple	\$58W 18.02' (1/16\$,BT)	3" Balm S18W 15.34' (1/16S,BT)		
i" Maple	N30W 13.03' (1/16S,BT)	4" Balm N68W 11.35' (1/16S,BT)		
₹ll trees	are blazed, scribed, and	All trees are blazed, scribed, and		
painted.	Measurements are to nail in	painted & Weamy mants are to nail in		
side of tree, bearings are magnetic. / side of tree, bearing are magnetic.				
igned by	leening of	July 15, 2014		

For the Michigan Department of Natural Resources,

20362

20361

E BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 Revised May 14, 1975 Revised Jan., 1983 Rervised Oct., 1995