LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Dickinson	Located In:	Corner Code #	
(County) ELCH TOWNSHIP			
. Public Land Survey	TR		
. Property Controlling	T R S 19 T 43N R 29V S 20 T 43N R 29V		
. Miscellaneous Property in Sec.	STR STR		
. Lot No, Re . Private Claims	corded Plat	 /2014	Register of Deeds Stamp & File Number A B C D E F G H I J K L M C C C C C C C C C C C C C C C C C C
Jeremy J. Pipp , i		1/2014 do hereby state	3
sove were in conformance with structions of the United States	regulations and rules therefore as r Department of the Interior, Bureau	rner points mentioned in lines 1 and 2 required in the current manual of survey of Land Management or by a decree of 4 and 5 above were in conformance with	ey 5 18 17 16 15 14 13
	rd of Land Surveyors or by a De	ecree of a Court of Law; established,	
OTE: Not more than 2 corn n this certificate.	ners, all in the same town and ra	ange, may be recorded	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36

- . Description of original monument and accessories and/or subsequent restoration:
- 13) Southeast One-Sixteenth corner of Section 19. Not set in original survey, no evidence of subsequent establishment.
- 08) Center-West One-Sixteenth corner of Section 20. Not set in original survey, no evidence of subsequent establishment.
- . Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 13) Corner position established at the intersection of the South and East One-Sixteenth lines of Section 19.
- 08) Corner position established mid-point and on-line between the Center One-Quarter corner and the West One-Quarter corner of Section 20.
- .. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

13)	DNR monument	(08) DNR monument
)" Cedar	N67E 20.66' (1/16S,BT)	6" Cedar N65E 6.69' (1/16S,BT)
2" Cedar	S38E 22.41' (1/16S,BT)	7" Cedar S40E 6.35' (1/16S,BT)
l2" Cedar	\$52W 9.72' (1/16\$,BT)	12" Cedar S51W 39.42' (1/16S,BT)
3" Cedar	N28W 8.22' (1/16S,BT)	7" Cedar N64W 16.24' (1/16S,BT)
	are blazed, scribed, and	All trees are blazed, scribed, and
painted. Measurements are to nail in		painted • mers genents are to nail in
side of tree, bearings are magnetic.		side at ince, learings are magnetic.
igned by	levening of	Date July 15, 2014

urveyor's Michigan License No.

For the Michigan Department of Natural Resources

PIPP ESTREGICE SIGNAL SURVEYOR

JEREMY J.

TATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 Revised May 14, 1975

20360