

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Dickinson	Located In:	Corner Code #
(County)		
ELCH TOWNSHIP		
Public Land Survey	T 43N R 29W	C07
	T 43N R 29W	C09
	T R	
Property Controlling	T R	
Section	T R	
	T R	
Miscellaneous	T R	
Property in Sec.	T R	
Lot No. _____, Recorded Plat _____		
Private Claims		

6/12/2014
Jeremy J. Pipp, in a field survey on 6/12/2014 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
in this certificate.

ii. Description of original monument and accessories and/or subsequent restoration:

C07) Section corner common to Sections 17, 18, 19, and 20. 1848: Harvey Mellen, DS. Set Sugar
section corner post witnessed by Sugar 8 S46E 22 links (14.52'), Yellow Birch 12 N57W 26 links
(17.16'). 1981: Michigan DNR (Keith Sackett PS#19006) Set 1" pipe with 4" Aluminum cap by
proportionate method witnessed by 7" Sugar N22W 17.0', 4" Sugar S57E 14.2', 6" Sugar N78E 18.5'.

C09) Section corner common to Sections 19, 20, 29, and 30. 1848: Harvey Mellen, DS. Set Cedar
section corner post witnessed by Cedar 10 S63W 15 links (9.90'), Cedar 8 N23E 33 links (21.78').
1981: Michigan DNR (Keith Sackett PS#19006) Set 1" pipe with 4" Aluminum cap from possible original
bearing tree witnessed by 4" Cedar S63W 26.2', 7" Cedar S76E 61.6', 5" Balsam N07E 2.7'.

iii. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C07) Accepted found MDNR Monument and Three NBT Witness (all living). Position is accepted as a
careful and faithful REESTABLISHMENT of the position of the original corner.

C09) Accepted found MDNR Monument, mound in place of possible OBT (S63W 15 links, per 1981 MDNR),
and Three NBT Witness (cedars living, balsam is 2 foot high stub). Position is accepted as a
careful and faithful PERPETUATION of the position of the original corner.

iv. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C07)	DNR monument	C09)	DNR monument
EX 10" Maple	N80E 18.74' (S 17,NBT)	EX 8" Cedar	S73E 62.28' (S 29,NBT)
EX 5" Maple	S54E 14.59' (S 20,NBT)	8" Cedar	S14W 48.20' (S 30,NBT)
7" Maple	S11W 17.63' (S 19,NBT)	EX 8" Cedar	S66W 26.34' (S 30,NBT)
EX 12" Maple	N17W 17.03' (S 18,NBT)	11" W. Birch	N71W 17.97' (S 19,NBT)
All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Parsonite rail was set West 1.5 feet.		All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Parsonite rail was set North 1.0 feet.	
Signed by _____		Signed by _____	

Surveyor's Michigan License No. 50447
For the Michigan Department of Natural Resources Forest Resource Division

