

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Form with fields for Dickinson (County), Located In, Corner Code #, Public Land Survey, Property Controlling Section, Miscellaneous Property in Sec., Lot No., Recorded Plat, Private Claims.

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number.

Jeremy J. Pipp, in a field survey on 6/12/2014 do hereby state

that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1. Description of original monument and accessories and/or subsequent restoration:

(C08) Quarter corner common to Sections 19 and 20. 1848: Harvey Mellen, DS. Set Cedar quarter section corner post witnessed by Sugar 12 S48E -- links (---'), White Pine 24 N67W 16 links (10.56'). 1981: Michigan DNR (Keith Sackett PS#19006) Set 1" pipe with 4" Aluminum cap from possible original bearing tree witnessed by 8" Sugar S43W 13.3', 8" Sugar N88E 9.8', 9" Sugar N47W 15.8', 9" Squared Basswood S83W 4 feet.

(D09) Quarter corner common to Sections 20 and 29. 1848: Harvey Mellen, DS. Set Ironwood quarter section corner post witnessed by White Pine 42 S34E 34 links (22.44'), Sugar 10 N49W 38 links (25.08'). 1981: Michigan DNR (Keith Sackett PS#19006) Set 1" pipe with 4" Aluminum cap by proportionate method witnessed by 8" Elm N40W 59.3', 12" Elm S49W 10.2'.

2. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C08) Accepted found MDNR Monument, trace remains of probable OBT (N67W 16 links, per 1981 MDNR), and Four NBT Witnesses (all living). Position is accepted as a careful and faithful PERPETUATION of the position of the original corner.

(D09) Accepted found 1" pipe 15 feet East of Centerline of N-S Road 6" below grade (SET MDNR cap on said existing monument) and existing mounds at positions of NBT Witnesses. Position is accepted as a careful and faithful REESTABLISHMENT of the position of the original corner.

3. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C08) DNR monument (D09) DNR monument
EX 10" Maple S89E 9.97' (1/4S,NBT) 5" Spruce N58E 19.62' (1/4S,NBT)
EX 12" Maple S46W 13.65' (1/4S,NBT) 7" Elm S34E 12.12' (1/4S,NBT)
EX 14" Basswood S88W 3.80' (1/4S,NBT) 7" Balsam S55E 52.12' (1/4S,NBT)
EX 13" Maple N44W 6.83' (1/4S,NBT) 5" Spruce N26W 69.66' (1/4S,NBT)
All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Carsonite rail was set North 1.5 feet. Signed by [Signature] Date July 15, 2014

Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, Forest Resource Division

