

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Form fields for Dickinson (County), Located In, Corner Code #, Public Land Survey, Property Controlling Section, Miscellaneous Property in Sec.

Form fields for Lot No., Recorded Plat, Private Claims

Text block containing survey date 6/09/2014, surveyor name Jeremy J. Pipp, and a statement of compliance with Michigan P.A. of 1970.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1. Description of original monument and accessories and/or subsequent restoration:

(D08) Center One-Quarter Corner of Section 20. Not set in original survey, no evidence of subsequent establishment.

(12) Center-South One-Sixteenth corner of Section 20. Not set in original survey, no evidence of subsequent establishment.

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D08) Corner position established at the intersection of the North-South and East-West One-Quarter lines of Section 20.

(12) Corner position established mid-point and on-line between the Center One-Quarter corner and the South One-Quarter corner of Section 20. Monument is +/-2 feet East of the West edge of Gravel of N-S Road and 6 inches below road surface.

2. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Table with 2 columns: (D08) DNR monument and (12) DNR monument. Rows list tree types (Balsam, Spruce, Poplar) and their dimensions/bearings.

All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

Signed by [Signature] Surveyor's Michigan License No. 50447 Date July 15, 2014

For the Michigan Department of Natural Resources, Forest Resource Division



Register of Deeds Stamp & File Number

13x13 grid table for Register of Deeds Stamp & File Number with columns A-M and rows 1-13.