

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Dickinson	Located In:	Corner Code #
(County)		
ELCH TOWNSHIP		
Public Land Survey	T 43N R 29W	E07
	T 43N R 29W	E08
	T R	
Property Controlling Section	S T R	
	S T R	
	S T R	
Miscellaneous Property in Sec.	S T R	
	S T R	
Lot No. , Recorded Plat		
Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

6/16/2014  
Jeremy J. Pipp, in a field survey on 6/16/2014 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
in this certificate.

1. Description of original monument and accessories and/or subsequent restoration:

(E07) Section corner common to Sections 16, 17, 20, and 21. 1848: Harvey Mellen, DS. Set Sugar  
section corner post witnessed by Ironwood 8 S31E 41 links (27.06'), Sugar 14 N38W 22 links  
(14.52'). 1981: Michigan DNR (Keith Sackett PS#19006) Set 1" pipe with 4" Aluminum cap at found  
most location witnessed by 7" Sugar N51W 8.0', 5" Sugar S85E 6.6', 7" Yellow Birch S87W 25.4'.

(E08) Quarter corner common to Sections 20 and 21. 1848: Harvey Mellen, DS. Set Cedar quarter  
section corner post witnessed by Cedar 6 N67E 22 links (14.52'), Cedar 8 N23W 9 links (5.94').  
1981: Michigan DNR (Keith Sackett PS#19006) Set 1" pipe with 4" Aluminum cap from possible original  
bearing trees witnessed by 9" Cedar N04W 16.3', 14" Cedar N47E 37.2'.

2. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E07) Accepted found MDNR Monument and Three NBT Witness (two living, SW NBT standing dead).  
Position is accepted as a careful and faithful REESTABLISHMENT of the position of the original  
corner.

(E08) Accepted found MDNR Monument, trace remains of possible OBT's (per 1981 MDNR), and two NBT  
Witnesses (living). Position is accepted as a careful and faithful PERPETUATION of the position of  
the original corner.

3. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E07)	DNR monument	(E08)	DNR monument
3" Maple	N55E 15.78' (S 16,NBT)	EX 13" Cedar	N04W 16.57' (1/4S,NBT)
EX 8" Maple	S77E 6.77' (S 21,NBT)	EX 14" Cedar	N47E 37.51' (1/4S,NBT)
4" Maple	S59W 19.62' (S 20,NBT)	14" Cedar	N81E 23.99' (1/4S,NBT)
EX 8" Maple	N44W 7.97' (S 17,NBT)	3" W. Birch	S79W 12.42' (1/4S,NBT)
All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Carsonite rail was set North 1.5 feet.		All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Carsonite rail was set North 1.5 feet.	
Signed by		July 15, 2014	

Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, Forest Resource Division

20370

20369