

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

DICKINSON COUNTY

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 43 N. XX R. 29 XX W.	C7, C9, A4
2. PROPERTY CONTROLLING IN SECTION 18	T. 43 N. XX R. 29 XX W.	16
3. MISCELLANEOUS PROPERTY IN SECTION	T. S. R. E. W.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Keith L. Sackett, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on See Below, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner C7: Original monument and accessories not found.

Corner C9: Found possible cedar B.T. S63°W 15 lk.

Corner A4: Original monument and accessories not found. Found old Sq. post and railroad bolt N11°W 7.5 ft.

Corner 16: Not set on original survey nor subsequently apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner C7: Restored 5-13-81 by double proportionate measurement.

Corner C9: Restored 5-18-81 from possible cedar B.T. fits good with other corners in area.

Corner A4: Restored 5-27-81 midway and on line between corners north and south.

Corner 16: Established 5-13-81 midway and on line between corners east and west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner C7: Set 1" I.D.x32" iron pipe with 4" alum. cap.
7" Sugar N22°W 17.0 ft. S18,NBT
4" Sugar S57°E 14.2 ft. S20,NBT
6" Sugar N78°E 18.5 ft. S17,NBT

Corner C9: Set 1" I.D.x32" iron pipe with 4" alum. cap.
4" Cedar S63°W 26.2 ft. S30,NBT
7" Cedar S76°E 61.6 ft. S29,NBT
5" Balsam N07°E 2.7 ft. S20,NBT

Corner A4: Set 1" I.D.x32" Iron Pipe with 4" alum. cap.
11" Spruce N32°W 19.7 ft. 1/2S,NBT
7" Cedar S29°E 40.1 ft. 1/2S,NBT
5" Balsam S49°W 51.9 ft. 1/2S,NBT

Corner 16: Set 1" I.D.x32" iron pipe with 4" alum. cap.
4" Sugar S86°W 7.5 ft. 1/16S,BT
10" Sugar N06°W 6.3 ft. 1/16S,BT
6" Sugar S72°E 14.2 ft. 1/16S,BT

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Keith L. Sackett
CHIEF OF SURVEY PARTY
MICHIGAN REGISTERED LAND SURVEYOR
Department of Natural Resources

DATE 10-22-81

SURVEYOR'S MICHIGAN REGISTRATION NO. 19006