## SURVEY & REMONUMENTATION

APR 2 7 1995

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

<b>f</b>	COMMISS	Filing Requirem	ent of Act 74, Mich. P.A. 19	70	•
Fo	r corners in		:	i EEA	§ J
	Dickinson (County)	Located In:	Corner Code -##		
					C) ;
1.	Public Land Survey	T 43N R 30W	H-5 & T-5	31.75	₽ ⊙
		T R			& OFF SE D
		T R T R	:		
2.	Property Controlling	_			φ <u>Π</u>
	in Section	S R		<u></u>	52
3.	Miscellaneous	S T R	1	Register of Deeds Stamp 8	File Number
	Property in Sec.	S R			
4	Lot No.	Recorded Plat	1		
		Trocorded Flat		A B C D E F G	HIJKLM
				2 6 5 4	-321
				3	<del>-                                     </del>
1	Rdward Kaziank	in a field survey on <u>Sept. 2</u>	10.01	4 7 8 9	-10-11-12-
do l	nereby certify that under re	quirements of P.A. 74, Michigan P.A. of 19	970, the corner points mentioned	5	- <b>†</b>
in li	nes 1 and 2 above were	n conformance with regulations and ru	les therefore as required in the	6 18 17 16	-15-14-13-
Mar	rent manual of survey hist ragement or by a decree o	ructions of the United States Departmer a Court of Law and/or that the corner po	into the interior, Bureau of Land ints mentioned in lines 3, 4 and 5	8 10 20 21	
abo	ve were in conformance w	ith the rules of the Michigan Board of La	nd Surveyors or by a Decree of a	9 1 20 -21	22 23 24
exp	ressed below:	re-established, monumented, re-monu	imented, recovered, found as	10 30 29 28	27-26-25
NO	TE: Not more than 4	corners, all in the same town and re	ange, may be recorded	11	20 25
	on this certificate			12 31 32 33	34 35 36
	Barrier to the state of			13	
A.		monument and accessories and/or	•	<b>-</b> - ,	
	H-5 Wood Post	Cedar 10 S31E 10 1ks	• Cedar 12 N38E 35	ī lks.	
	I-5 Wood Post	Cedar 12 S28E 09 1ks	. Cedar 14 N21W 33	3 1ks.	
				ACCEPTED BY THE DIC SURVEY PEER GROUP	AS THE OFFICIAL
				CORNER UNDER MICHIG	GAN PUBLIC ACT
				345 OF 1990 AT A ME	ETING HELD ON
				RAP.	
В	Description of corner of	widence found and/or method appli	iad in ractorina or reactablishin	COUNTY P	REPRESENTATIVE
υ.	Description of corner evidence found and/or method applied in restoring or reestablishing corner:  H-5 No evidence of original corner or accessories found. Set the Quarter Corner by				
		easurment at the mid-poin			
	is mile to the e	ast and west.			
	I-5 No evidence of original corner or accessories found. Thus, set corner by proport-				
	ionate measurment. For north-south position: The distance from the south edge of the Ford River between Sections 14 and 15 to the corner of Sections 2, 3, 10 and 11 is				
	5773.07 feet. Proportionately then the corner should be set 5308.57 feet South of the				
	corner common to Sections 2,3, 10 and 11. For east-west position: The section corner				
l mile east and the section corner 2 miles west are in with a distance of 15,890.88 feet					
	between them.	Proportionately then the o Sections 11, 12, 13 and	corner should be set	5307.99 feet West	of the
		The Ford River is 464.5			s above
			:	. 022702 \$	
C.	Description of monume	nt for corner and accessories estab	olished to perpetuate locating t	he position of the corner	
H-5		on County Survey cap on a			
	Cedar 10 N	63E 18.53 feet. Cedar			0.48 feet.
	Cedar 5 S	34E 13.70 feet.			4
	T-5 2½ inch Di	ckinson County Survey cap	on a three foot Alum	່ ນຳກຸນໜ້າວຢູ່	
	Cedar 8 N	05W 30.07 feet. Cedar 6	N65E 28.63 feet.	Cedar 6 S59E 3h.	75 feet.
		10 N 4.00 feet.			E MILE
				Fit U	******
		;		F se se F	DWARD **
		,		As & KA	ZIANKA 💃 🗷
	Q n	1 4			LAND
Sign	ed by 6 Kenand	Kagooke	Date <u>Septem</u>	ber 6, 19 SU	IRVEYOR
Surveyor's Michigan License No. 14765 14765 FORM APPROVED BY MICHIGAN STANDBOARD OF PAND SURVEYORS, JAN 20 1971					
			TUAR APPA	TOP-	SHEVISED MAN 19. 19.
		1.1	Page 1	11)	LANS SEGUAN C1983
		Liber 2	· lage 1	U de	A STATE OF THE STA