

also T44N-R28W M07

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #
(County)		
WEST BRANCH TOWNSHIP		
1. Public Land Survey	T 44N R 27W	A07
	T 44N R 27W	B07
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

9/16/2013AD  
Jeremy J. Pipp, in a field survey on 9/16/2013AD do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(A07) Section corner common to Sections 13, 18, 19, and 24. 1846: Austin Burt, DS. Set Cedar Section corner post witnessed by Spruce 10 S30W 41 links (27.06'), Spruce 10 N58E 19 links (12.54'), Cedar 12 S45E 40 links (26.40'). 1984: Michigan DNR (David Babbitt PS#21558) Set 1" pipe with 4" Aluminum cap witnessed by 20" W. Pine N01W 63.8', 6" Maple N51W 47.9', 7" Aspen S84W 39.7', SW point on Boulder S32E 17.5'.

(B07) Quarter corner common to Sections 18 and 19. 1850: John Burt, DS. Set Cedar quarter section corner post witnessed by Cedar 10 S45W 17 links (11.22'), Cedar 10 N52E 8 links (5.28'). 1984: Michigan DNR (David Babbitt PS#21558) Set 1" pipe with 4" Aluminum cap witnessed by 4" Balsam N79E 18.5', 5" Black Spruce S22E 38.0', 5" Black Spruce N84W 35.9', 4" Balsam S88E 63.3'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A07) Accepted found MDNR Monument and Three existing NBT Witnesses (NW Maple has been cut). Position is accepted as a careful and faithful REESTABLISHMENT of the position of the original corner.

(B07) Accepted found MDNR Monument and four existing NBT Witnesses (two living, two dead). Position is accepted as a careful and faithful REESTABLISHMENT of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A07) DNR monument  
EX 30" W. Pine North 64.2' (S 18,NBT)  
6" Maple S40E 38.5' (S 19,NBT)  
5" Balsam S36W 8.48' (S 24,NBT)  
EX 13" Poplar S88W 39.87' (S 12,NBT)  
All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Carsonite rail was set North 1.5 feet.

Signed by  
Surveyor's Michigan License No. 50447

(B07) DNR monument  
12" Tamarack N55E 19.55' (1/4S,NBT)  
EX 6" B. Spruce S16E 38.03' (1/4S,NBT)  
6" B. Spruce S33W 27.43' (1/4S,NBT)  
7" B. Spruce N16W 11.48' (1/4S,NBT)  
All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Carsonite rail was set North 1.5 feet.

Date  
October 1, 2013

For the Michigan Department of Natural Resources, Forest Reserve Division

20281

20282

