

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>44N</u> N. S., R. <u>27W</u> E. W.	<u>B-9, C-8</u>
2. PROPERTY CONTROLL- ING IN SECTION_____	, T. _____ N. S., R. _____ E. W.	_____
3. MISCELLANEOUS PROPERTY IN SECTION_____	, T. _____ N. S., R. _____ E. W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, David Babbitt, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 27, 1984, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- B-9. South 1/4 corner of Section 19. Cedar 10 for 1/4 sec. cor.
Spruce 14 S69E - 31 Lks.
C-8. East 1/4 corner of Section 19. Sugar 1/4 sec. post.
Y. Birch 18 N36W 30 Lks.
Sugar 18 S17E 17 Lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- B-9. Set by single proportion between the SE and SW section corners of Section 19.
Swamp edges 2-1/2 chs. East and 2.00 Chs. West fit well.

- C-8. Set MPOL between the NE and SE section corners of Section 19.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | |
|--------------------------------|-----------------------------|
| B-9. D.N.R. Monument | C-8. 1" pipe, 4" alum. cap. |
| 11" W. Spruce - S87°E - 107.1' | 4" Aspen N68°E 31.65' |
| 6" W. Spruce N30E - 47.7' | 4" Aspen S60°E 21.50' |
| 9" W. Spruce N21°W - 37.5' | 10" Aspen S32°W 8.45' |
| 8" W. Spruce S85W - 94.8' | 9" Aspen N55°W 14.05' |

SIGNED BY

David B. Babbitt

DATE

1-16-85

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

DATE