

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Dickinson (County) Located In: Corner Code #
WEST BRANCH TOWNSHIP
Public Land Survey
Property Controlling Section
Miscellaneous Property in Sec.
Lot No. Recorded Plat
Private Claims

Jeremy J. Pipp, in a field survey on 9/03/2014 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
in this certificate.

1. Description of original monument and accessories and/or subsequent restoration:

(I04) Quarter corner common to Sections 10 and 11. 1850: John Burt, DS. Set Cedar
quarter section post witnessed by Spruce 10 S56E 16 links (10.56'), W. Pine 8 N21W 16
links (10.56'). No evidence of subsequent establishment.

2. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I04) No evidence of original survey. Location has been altered by logging activities;
corner falls 55 feet East of woods road in area of regrowth. Corner position reestablished
by single proportionate measurement between the Northeast corner and the Southeast corner
of Section 10. Position is accepted as a careful and faithful REESTABLISHMENT of the
position of the original corner.

3. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I04) DNR monument
4" Poplar N57E 12.89' (1/4S,NBT)
10" Spruce S55E 16.47' (1/4S,NBT)
5" Poplar S60W 16.62' (1/4S,NBT)
5" Balsam N34W 27.95' (1/4S,NBT)
All trees are blazed, scribed, painted,
and signed. Measurements are to nail in
side of tree, bearings are magnetic. A
Carsonite rail was set East 1.5 feet.

Signed by
Surveyor's Michigan License No. 50447



September 10, 2014

For the Michigan Department of Natural Resources, Forest Resources Division