

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>44</u> ^{N.} S. R. <u>29</u> ^{W.} E.	<u>C8</u>
2. PROPERTY CONTROLL- ING IN SECTION <u>20</u>	, T. <u>44</u> ^{N.} S. R. <u>29</u> ^{W.} E.	<u>10</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____	, T. _____ ^{N.} S. R. _____ ^{E.} W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

**REGISTER OF DEEDS STAMP AND
FILING NUMBER**

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on Sept. 15, 19 75, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner C8 (1/4 corner between Sections 19 & 20, T44N, R29W):

Cedar Post	(Not found. No subsequent monuments found.)
Hemlock 6 S22E 57	(" " " " accessories ")
W. Pine 18 N56W 31	(" " " " " ")

Corner 10 (South 1/16 corner between Sections 19 & 20, T44N, R29W):

Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner C8: Re-established proportionately on line between original line trees
4.298 ch. S and 32.043 ch. N. (Record distances are 4.31 ch. and 32.13
ch., respectively).

Corner 10: Established on line between Sec. Cor. 19.905 ch. S and 1/4 cor. 19.905
ch. N. Corner falls about 1 chain S of rock ledge.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner C8: 1" I.D. x 36" iron pipe with 3 1/2" aluminum cap.

Red Pine 16 N50°W (mag.) 41.9 ft. "1/4S, NBT"

Red Pine 5 S80°E (mag.) 8.0 ft. "1/4S, NBT"

Corner 10: 1" I.D. x 36" iron pipe with 3 1/2" aluminum cap

Red Pine 12 N84°W (true bearing) 5.0 ft. "1/16S, BT"

Red Pine 5 N 60°E (true bearing) 7.9 ft. "1/16S, BT"

Note: Strong local magnetic attraction at this corner. Variation is 11°50' East.

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Arthur O. Enger DATE January 26, 1976

CHIEF OF SURVEY PARTY
Arthur O. Enger
MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger
Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

