

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____ T. _____ N. _____ E. _____ S., R. _____ W.		
2. PROPERTY CONTROLLING IN SECTION _____ 9 _____ T. _____ 44 _____ N. _____ E. _____ S., R. _____ 29 _____ W.		1 & 3
3. MISCELLANEOUS PROPERTY IN SECTION _____ T. _____ N. _____ E. _____ S., R. _____ W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner 1 (West 1/16 corner between Sections 4 & 9, T44N, R29W):

Not established in original survey nor subsequently, apparently.

Corner 3 (North 1/16 corner between Sections 8 & 9, T44N, R29W):

Not established in original survey and by approximation only, subsequently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner 1: Established 9/23/75 on line between Sec. Cor. 19.944 ch. W and 1/4 cor. 19.945 Ch. E.

Corner 3: Established 10/7/75 on line between original line trees 15.115 ch. S and 13.118 ch. N (Record distance between line trees is 28.28 ch., measured distance is 28.233 ch.) Found a squared post S38°W 15.7 ft. for an approximate corner. As placed, this corner bears N0°08'40"W 20.026 ch. from original 1/4 cor. bet. Sec. 8 & 9 and S0°18'40"E 20.183 ch. from original Sec. Cor. 4, 5, 8, & 9.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner 1: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
Cedar 10 S30°W (mag.) 12.9 ft. "1/16S, BT"
Cedar 5 N30°W (mag.) 12.7 ft. "1/16S, BT"

Corner 3: 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.
Tamarack 7 S82°W (mag.) 29.8 ft. "1/16S, BT"
Cedar 6 S20°E (mag.) 45.7 ft. "1/16S, BT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY Carl R. Johnson DATE January 21, 1976

APPROVED AND SIGNED BY Arthur O. Enger DATE January 21, 1976

MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581