

**LAND CORNER RECORDATION CERTIFICATE**  
**FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970**

FOR CORNERS OF—:	DICKINSON COUNTY LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. <u>44</u> N. <u>X</u> R. <u>29</u> K. <u>W.</u>		E-13
2. PROPERTY CONTROLLING IN SECTION _____, T. _____ S., R. _____ E. <u>W.</u>		
3. MISCELLANEOUS PROPERTY IN SECTION _____, T. _____ S., R. _____ E. <u>W.</u>		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		
		REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 13, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Section Corner 4, 5, 32, & 33, T43-44N, R29W  
Wood post (Not found. Found recent maple stake in place.)  
W. Pine N51°W 15 (Found. Also found Buckler's NBT's as follows:  
W. Birch 6 S87°E 14 lks. "S 4, NBT"  
R. Oak 7 S44°W 86 lks. "S 5, NBT"  
Aspen 7 N22°W 20 1/2 lks. "S32, NBT" (dead)

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Replaced maple stake with monument described below. Notes by B. D. Buckler, R.L.S., indicate he set a 1" iron pipe with 4" brass cap from the W. Pine BT. Pipe now missing, but Buckler may have only witnessed the corner position on 11-20-1957, intending to come back at another time to install the pipe, but never actually did, as it does not appear as though one had ever been in the ground. Monument described below was set from Buckler's NBT's. Buckler's W. Birch is now 9" dia., his R. Oak 14", and the aspen dead.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.  
Red Maple 4 N60°W (mag.) 39.4 ft. "S32, NBT"

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY Arthur O. Enger DATE March 15, 1979

CHIEF OF SURVEY PARTY  
MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

