

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. ⁴⁴ NR 29 W

Dickinson

COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 9 and 16

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER Cedar 7" S 16 E 26 links, marked 1/4 S NBT

Cedar 10" S 60 W 29 links, marked 1/4 S NBT

Distances measured from NBT notch to center on brass cap.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

Corner was replaced from two original cedar bearing trees in poor condition. Both trees down but in proper position. Found scar tissue and axe marks on Cedar 20 S 9 W 15 links. All markings obliterated in remains of Cedar 14 W 64 E 18 links. Old cruisers marks and old cedar blazed 4 sides for corner near by. Have good corner 1/2 miles west. Distance chained with Clarence Ryberg. Old blazed line runs through corner.

Corner was found while cruising timber in this area.

Corner placed and witnessed on 22 August 1957 with Clarence Ryberg.

SURVEYORS SEAL

Henry S. Peterson

SIGNED Henry S. Peterson
REGISTERED LAND SURVEYOR

DATE 8/29/57