SURVEY & REMONUMENTATION

MAR 0 4 1998

STATE OF MICHIGAN EMMET COUNTY RECORDED

LAND CORNER RECORDATION CERTIFICATE 97 DEC 30 PM 4: 15 Filing Requirement of Act 74, Mich. P.A. 1970

For corners in SECTION	1 Leo a 1
EMMET Located In: Corner Co	de # Ellerne de Ajes REGISTER DE DEEDS
(County) RESORT TOWNSHIP	REGISTER OF DEFOS
1. Public Land Survey T 34N R 6 W L-6 T R	_
ECRP# 150 T R	_
2. Property Controlling S T R	LIBER A PAGE 233
in Section S T R	
3. Miscellaneous S T R	Register of Deeds Stamp & File Number
Property in Sec. STR	
4. Lot No, Recorded Plat	ABCDEFGHIJKL
5. Private Claims	
	2 6 5 4 3 2 1 1
	3
I, Richard E. Oelke in a field survey on 19 December	$\frac{1997}{}$ 4 $\frac{1}{7}$ $\frac{8}{}$ $\frac{9}{}$ $\frac{10}{}$ $\frac{11}{}$ $\frac{12}{}$
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the mentioned in lines 1 and 2 above were in conformance with regulations and rules	therefore as
required in the current manual of survey instructions of the United States Department o	f the Interior, $6 \begin{array}{ c c c c c c c c c c c c c c c c c c c$
Bureau of Land Management or by a decree of a Court of Law and /or that the of mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michi	gen Board of
Land Surveyors or by a Decree of a Court of Law; established, re-established, r	monumented, 8 19 20 21 22 23 24
re-monumented, recovered, found as expressed below:	9
NOTE: Not more that 4 corners, all in the same town and range, may be reco	
on this certificate.	
	12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent resstoration:	13
L-6 Center 1/4 corner of sec. 13, T34N, R6W	
See Outline of Corner History on back.	
Palmer set cedar post in 1902 A T-iron was found by Young in 196	31 and has been used till present.
Description of corner evidence found and/or method applied in restoring or reestablishing corner: APPROVED LAND CO P.A. 345 OF 1990	
L-6 Center 1/4 corner of sec. 13, T34N, R6W	
In a monument box, found T-iron, 3' N of CL Intertown Rd and CL of	Eppler Rd.
WITNESSED AS FOLLOWS:	12.30.17
N45°E 32.54' p.p., tagged in NW face	
C. Description of monument for corner and accessories established to perpetuate locat	ing the position of the corner:
L-6 Center 1/4 corner of sec. 13, T34N, R6W	
Replaced the T-iron with a 2" diameter, 30" long PVC post with a bra Program cap This position is within .3' of the mathematical position careful establishment of the center 1/4 corner	

p.p., tagged PS# 33983 in NW face p.p., tagged PS# 33983 in NE face S42°E 34.01' 55.71 S25°W 8" spruce, tagged PS# 33983 in SE face N81°W 163.32' p.p., tagged PS# 33983 in N face Signed by __ Date <u>19 December 1997</u> Surveyor's Michigan License No. 33983

NEW WITNESSES AS FOLLOWS:

N39°E

35.49'

OF11110 FORM AFPROVED BY MICHIGAN STATE BOARD OF LAND SAME ASS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983

DF MICH

RICHARD E

OELKE PROFESSIONAL

SURVEYOR No.

33983

EMMET COUNTY REMONUMENTATION PROGRAM CORNER NO. 150

34-6-L6
T34N R6W CENTER 1/4 CORNER SECTION 13
INTERTOWN AND EPPLER ROAD

Date Surveyor	Found	Witnesses	
1902 Palmer	Set Cedar Post		
1961 G. Young	Survey for Ernst showes relationship between corners		
1963 G. Young	Fd. "T" iron at intersection	8	N.
			14
1971 J. Green	Fd. "T" iron	1) N14°E 32.90'	P. P.
	survey for Glodsmith.	2) S15°E 26.10'	14" Maple
1972 G. Young	Fd. "T" iron	2) 11	
1972 G. 10dng	rd. "I" iron	3) N44°E 32.40′ 4) S20°E 25.48′	P.P. 12" Maple
		5) N50°W 64.15'	4" Mtn. Ash
1971-1977 J. Green	Fd. "T" iron surveys for Melvin Kauffman,	Holzschu, Foster	
1974 G. Young	Fd. "T" iron, survey for Clayton Eppler		
1000 G W			
1980 G. Young .	Fd. Corner, Plat		
1995 T. Swenor	Fd. Corner survey for Brecheisen		

And the second s

SURVEY & REMONUMENTATION

MAR 0 4 1998

SECTION