

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Gogebic  
(County)

Located In:

Corner Code #

- 1. Public Land Survey
- 2. Property Controlling in Section
- 3. Miscellaneous Property in Sec.

T 44N R 41W  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_

G-5,6  
014  
014  
RRD  
10/18/98  
Approved  
5/25/94

**PEER GROUP**

Richard L. Brown

Register's Office }  
Gogebic County } ss.

Received for record the  
1<sup>st</sup> day of JUNE  
A. D. 1994 at 1:45 o'clock  
P m., and recorded in  
Liber 5 of CORNERS  
on page 63  
Richard J. Brown  
Register of Deeds  
Register of Deeds Stamp & File Number

- 4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
- 5. Private Claims \_\_\_\_\_

Corner G-5,6 (South Meander Corner between Sections 15 and 16 on the North shore of West Bay Lake)

I, Gary L. Pisoni, in a field survey on December 21, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by A. Merryweather, U.S. Deputy Surveyor on July 5, 1852.  
Original corner: 3" Yellow Birch Tree  
Original Bearing Trees:  
White Pine 20" N 60°W 14 lks (9.24 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original corner evidence found. Corner position found marked by a 1 3/4" x 3 feet long iron pipe located on the North shore of West Bay Lake. Iron pipe set by unknown person. Iron pipe has been used for numerous surveys in Sections 15 and 16. I accept the iron pipe as the best available evidence for restoring the corner position.  
Replaced iron pipe with an aluminum rod monument as described below. Layed pipe next to monument.  
Monument is located 17 feet from waters edge.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, I set a 3/4" outside diameter by 3 feet long aluminum rod monument with a 3" cast aluminum cap, stamped to read: T44N, R41W, S-16, S-15, M.C., 1993, RLS- 27457 from which I established the following new blazed and scribed existing bearing trees: (all measurements taken to a nail in side of tree)

Cedar	13"	N 10°W	9.82 feet
Yellow Birch	18"	West	18.53 feet
Hemlock	15"	S 01°E	12.38 feet
Steel Sign Post		East	1.00 feet



Signed by Gary L. Pisoni Date 4-1-94  
Surveyor's Michigan License No. 27457