SUMVEY & REMONUMENTATION

AUG 0 8 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Register's Office Cogebic County

COMMING	LAND COIN	ER RECORDATION CERTIFICATION F.A.	4070	TU		ecord the
For corners dogebic	Located in:	Corner Code #		. 19 <u>97. a</u> t	•	
(County)			Am D	P.m.,		
Public Land Survey	Section 4 45N R 41W 44N R 41W	EF-1 018	ED D	nga 163	M.K.	ibak
2. Property Controlling in Section 3. Miscellaneous Property in Section	T R S T R S T R S T R	10/18/98	Register of De	ecds Stamp		
4. Lot No, R 5. Private Claims	ecorded Plat		A B	C D E F	G H	I J K Ł M
Meander corner sections 33 and 4 T44-45N R41W.					+	
do hereby certify that under req in lines 1 and 2 above were in commanual of survey instructions Management or by a decree of 5 above were in conformance Decree of a Court of Law; estat as expressed below:	uirements of P.A. 74, Michigan Fonformance with regulations and of the United States Depart a Court of Law and/or that the with the rules of the Michigan Folished, re-established, monument	, 19 A. of 1970, the corner points ment in rules therefore as required in the corner of the Interior, Bureau of corner points mentioned in lines 3, Board of Professional Surveyors or ented, re-monumented, recovered,	ioned 6 18— urrent 7 Land 7 4 and 8—19— by a 9		22-	11 - 12 - 13 - 13 - 13 - 13 - 13 - 13 -
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.				32 -33	34	35 36
A Description of original	monument and accessories	and/or subsequent restoration	1:	•		

On July 29, 1847, William Burt, D.S. established the corner and the following bearing trees: 12" Cedar N47°E 6 links 9" Cedar S79°W 18 links

In 1980 Richard Drahn, R.L. S. #21564 found a Michigan Conservation Department monument and established witness objects (see Section C below). Recorded Liber 3, page 289.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found a monument and witness objects as noted in Richard Drahn's Certificate. The corner was set by Shadko, a surveyor for the Michigan Conservation Dept. in 1943. He found a 4"x 4" cedar stake inscribed 1225 ft. to the E 1/4 corner as shown in his notes I received from the MDNR surveyor Steve Syszkoski.

Corner research on file.

PETDESE IPATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Block foundation corner of building -S06°W -44.00 ft. (existing) N46°W 0.56 ft. (existing) Sign rail N82°E Sign rail 49.37 ft. (existing) 5/8" x 24" rebar \$86°E 156.86 ft. (new) 10.99 ft. (new) 6" Red pine N13°E 18.27 ft. (new) Light Pole S31°W

JOHN R. GARSKE AND RYEYOR 160. 28410 LAND

Signed by

higan License No.

REVISED MAY 14, 1975 REVISED JAN., 1983